

60630094


2. Approving Competent Authority / Country A / Germany		3. Form Tracking Number 15373769 000000001	
AUTHORISED RELEASE CERTIFICATE EASA FORM 1			
Approved Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany			
7. Description MODULE ASSY, DOOR WARNING	8. Part No. 233A3207-4	9. Eligibility (*) UNKNOWN	10. Qty 1
11. Serial / Batch No. D00086		12. Status / Work INSPECTED / TESTED	
FSCM 81205 ATA 3111 TPF aniana Fluggesellschaft mbH (GMI) R1639509 MK-No. 10 Pack Code 00 Resp. Workshop 32224010 Workshop Station HAM305			
Opr. Hours N/A N/A N/A 0 Cycle N/A N/A N/A 0 Opr. Day N/A N/A N/A 0 PERFORMED IN ACCORDANCE WITH CMM 31-11-26 / CMDS ISSUE 12 Life parts must be accompanied by maintenance history ifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☒ Part-145.A.50 Release to Service Other Regulation specified in block 13 Certifies that unless otherwise specified in block 13, the work identified in block 12 and described in block 13, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.			
20. Authorised Signature 		21. Certificate / Approval Ref. Number DE.145.0001	
22. Name 086398, Andre Weidenhausen		23. Date (d/m/y) 12/Aug/2009	

It is important to understand that the existence of the document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer works in accordance with the national regulations of the Airworthiness Authority different from the Airworthiness Authority specified in block 1 it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority specified in block 1.

Statements 14 and 19 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report



Customer Order No.	R1639509		Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany	Certificate Ref. No.	60630094	15373769 000000001
Customer	Germania Fluggesellschaft mbH (GMI)			Work order/Contract/Invoice		60630094
No. as received	233A3207-4	Serial No. as received	D00086	Description	MODULE ASSY, DOOR WARNING	
No. as dispatched	233A3207-4	Serial No. as dispatched	D00086	Responsible Workshop	32224010	
Reason for removal	NO INDICATION FOR SERVICE DOOR OPEN			Modification Status as dispatched according to Mod-Label		
Findings	None					
Conclusion	Test performed several times, all test steps passed.				N/A	
Work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not agreed by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) der.				Name	86398, Andre Weidenhausen	
Form 30992 D-06 (HAM TQ/E) Printed in the Federal Republic of Germany				Date (d/m/y)	12/Aug/2009	