

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 112929	
4. Organization Name and Address: Continental Aircraft Support, Inc., 13960 N.W. 60th Ave., Miami Lakes, FL 33014 (ZN9R863X)					
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	DIGITAL / ANALOG ADAPTER	DG1035AB03	1 EA	1960	INSPECTED / TESTED

12. Remarks: In accordance with
Publication No: 34-21-16 Revision: 11 Revision Date: Feb/28/2008
Publication No: 34-21-16 Revision: 9 Revision Date: Oct/01/2006
MFG: HONEYWELL
A/D, Mod., S/B, Accomplished: NONE

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA 145-5605

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b. Authorized Signature: 	14c. Approval/Certificate No.: ZN9R863X
14d. Name (Typed or Printed): NATAN HERNANDEZ	14e. Date (dd/mm/yyyy): 15/Feb/2021

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Continental Aircraft Support, Inc.
13960 NW 60th Ave.
Miami Lakes, FL 33014 USA
Tel. (305) 883-6100
Fax (305) 817-9323
Email: info@ContinentalAircraft.com
www.ContinentalAircraft.com



ISO 9001:2015 Registered
FAA CRS# ZN9R863X
EASA 145.5605

Teardown Report No.: 112929

Part No.: DG1035AB03	S/N Received: 1960	Date: 1/27/2021
Desc.: DIGITAL / ANALOG ADAPTER	Mfr.: HONEYWELL	R/O: WR9200
Publication: 34-21-16	Rev.: 11, 2/28/2008	Manual No.: E7261

Work Requested: REPAIR

Trouble Reported / Special Instructions: FAILED ON FIT "FAILUR CODE ON ISDU "05" ; NO SPECIAL INSTRUCTIONS REPORTED DUAL RELEASE REQUESTED.

Receiving Inspection:

WORK SCOPE

P/N AND S/N VERIFIED TO REPAIR ORDER. NO SHIPPING DAMAGE NOTED.

Shop Findings:

PASSES MANUFACTURER'S FUNCTIONAL TEST. UNABLE TO DUPLICATE TROUBLE REPORTED. NO TROUBLE FOUND. TESTING AND INSPECTION DEEMS UNIT READY FOR RETURN TO SERVICE. WARRANTY DENIED.

Tech Pub Checked: ☒ Yes ☐ No ☐ N/A

Initial Test: ☒ Pass ☐ Fail ☐ N/A

P/N & S/N Checked: ☒ Yes ☐ No ☐ N/A

Disassembled: ☐ Yes ☒ No ☐ N/A

Malfunction Verified: ☐ Yes ☒ No ☐ N/A

Hidden Damage Insp. Req'd.: ☐ Yes ☒ No

Corrective Action:

INSPECTED AND TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.

Cleaned / Painted: ☒ Yes ☐ No ☐ N/A

Passed Final Test: ☒ Yes ☐ No ☐ N/A

Service Perfmd.: INSPECTED / TESTED

Reworked: ☐ Yes ☒ No ☐ N/A

NDT: ☐ Yes ☐ No ☒ N/A

Completion P/N: DG1035AB03

Returned Assembled: ☒ Yes ☐ No ☐ N/A

Release Insp.: ☒ Yes ☐ No ☐ N/A

Completion S/N: 1960

List of Airworthiness Directives, Modifications, or Service Bulletins Accomplished:

NONE

Maintenance Release

The aircraft component identified above was serviced and inspected in accordance with current Federal Aviation Regulations and Manufacturers Maintenance Manual and was found to be airworthy for return to service. Pertinent details of the work performed is on file at our facility under the work order number stated above.

Authorized Signature: _____

Name: NATAN HERNANDEZ

Date: 15/Feb/2021