


ing Competent
rthly / Country

2.

61903667



3. Form Tracking Number

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

21592807 00000001

ition Name and Address.



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61903667

7. Description

8. Part No.

EXCHANGER-PRECOOLER

3732A010000

9. Qty.

1

10. Serial No.

2307

11. Status / Work

OVERHAULED

ion RO220623

ATA 3611

TP O

MK-No. 10

Pack Code 00

Resp. Workshop 33343050

Workshop Station HAM143

hours Cycle Opr. Day

DOWN UNKNOWN UNKNOWN

0 0 0

0 0 0

0 0 0

36-11-19 ISSUE 017

36-11-19 ISSUE 017

FAA Certificate No.: DLA225D

Return to Service in Accordance with 14 CFR part 43

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under

that the items identified above were manufactured in conformity to:
proved design data and are in condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ Part-145.A.50 Release to Service
Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

☒ Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents

☒ Other Regulation specified in block 12

Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

550584

14d. Name

Bryan-Jason Kubeil

14c. Certificate / Approval Ref. Number

DE.145.0001

14e. Date (dd mm yy)

18 Oct 2022

1 - Issue 3

LER RESPONSIBILITIES

icate does not automatically constitute authority to install the item(s).

3 user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1.

s in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certificate issued in accordance with the national regulations by

10 H-21 (HAM TQA)

Order No.

RO220623



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

61903667

Certificate Ref. No.

21592807 00000001

Work Order/Contract/Invoice

61903667

2

10

2307

3732A010000

Serial No. as dispatched

2307

**or removal
REQUESTED**

Responsible Workshop

33343050

[illegible]

Modification Status according to Mod-Label

BENT,

See Unit Mod-Label if equipped

D,
WELDED,
RENEWED,
STRAIGHTENED,
THES POLISHED,
TEST O.K.,
LOSS TEST O.K.,
ON THE TUBES ARE ACCEPTABLE AS PER LIEBHERR SPM 20-00-01 REV.2, DATED FEB 10/20

incited above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder

992 H-19) (HAM T/CE-Q)

550584, Bryan-Jason Kubeil

Date (dd mmm yyyy)

18 Oct 2022