


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 1081100													
4. Organization Name and Address: UNICORP SYSTEMS, INC 2625 W. 40th Place Tulsa, Ok 74107				5. Work Order/Contract/Invoice Number: R395814														
6. Item:		7. Description:		8. Part Number:	9. Quantity:	10. Serial Number:												
1		HEADSET		64300-000	1	N/A												
				11. Status/Work: REPAIRED														
12. Remarks: Unicorp Systems, Inc. certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the Aircraft Component is considered ready for release to service under EASA Approval Certificate number: EASA 145.4974. Full details of the work carried out can be found on form WO-1C with the tracking number found in block 3. The work specified in block 11 has been accomplished in accordance with the following FAA approved data: CMM 23-50-06 REV. 6 Dated 1-JUN-2000 Parts Used <table style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Qty</th> <th style="text-align: left;">MPN</th> <th style="text-align: left;">Description</th> <th style="text-align: left;">R1</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>64319-000</td> <td>MIC ASSY.</td> <td>R1177894</td> </tr> <tr> <td>1</td> <td>590637-000</td> <td>CLOTHING CLIP ASSY.</td> <td>R1168973</td> </tr> </tbody> </table>							Qty	MPN	Description	R1	1	64319-000	MIC ASSY.	R1177894	1	590637-000	CLOTHING CLIP ASSY.	R1168973
Qty	MPN	Description	R1															
1	64319-000	MIC ASSY.	R1177894															
1	590637-000	CLOTHING CLIP ASSY.	R1168973															
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.				14a <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.														
13b Authorized Signature:		13c Approval/Authorization No.:		14b Authorized Signature:		14c Approval/Certificate No.:												
						IL2R902K												
13d Name (Typed or Printed):		13e Date (dd/mm/yyyy):		14d Name (Typed or Printed):		14e Date (dd/mm/yyyy):												
				LUNDY		08 SEP 2022												
User/Installer Responsibilities																		
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.																		

www.UnicorpOK.com

[REDACTED]

UNICORP Systems, Inc.
2625 W. 40th Place Tulsa, OK 74107

(918) 446-0393 Fax (918) 446-3910

Date Unit Recv'd 06/08/22

Work Order# **1081100**

Manufacturer **TELEX**

Unit Part# 64300-000

Unit Serial # *NONE*

Customer **AJ WALTER (AVIATION) LTD**

Cust Order # R395814

Inspection Instructions

	<u>Manual</u>	<u>Rev.</u>	<u>Date</u>
Serv. Authority	23-50-06	6	06/01/00
Insp. Authority	23-50-06	6	06/01/00

<u>Work Record</u>	Supervisor's Name	Technician Signature	Date	<u>Parts Replaced</u>		Initials
No Mods Marked				Qty	R# Number	Tech
Reason for Removal :	C/S			()	760273 (renew)	Joh
USI Seal : (None, OK, Broken)				I	107894 - mic	DJF
Mods :	no mods required					
Preliminary Inspection :	clothing clip missing					
	E-163	[Signature]	6/9/22			
	Tested unit per comm Found microphone not needed replace listed below:					
	ENS	[Signature]	6/8/22			
	Repaired : mic assy					
	Tested per Comm 23-50-06					
	Passed per comm					
	No Complaint					
	Passed final per comm-					
	Young DJT July 9-8-22					
				Final Audit of Work/Inspection Record		Audit Passed USI 130
				Disposition of Unit Date 08 SEP 2022		
				Authorized Signature [Signature]		
				Return to Customer		
				<input checked="" type="checkbox"/> Released to Service (8130-3) Maintenance Release Used.		
				<input type="checkbox"/> Other Disposition (Specify):		
				VS1 VS2 10 VS3 Z		

Warranty

Overhaul

Rev: 4 24-J