

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 247791	
4. Organization Name and Address: Aero Accessories & Repair, Inc. FAA CERT #77AR783B 15501 SW 29TH ST. SUITE#201 MIRAMAR, FL 33027 Ph: 954-266-1300, FAA Approval Holder: 77AR783B				5. Work Order/Contract/Invoice Number: 59105 T41753	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	BRAKE VALVE ASSEMBLY	274N1051-3	1	01975	OVERHAULED
12. Remarks: The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above. TSO: 0:00 S/B and A/D: None Applicable. OEM CMM: 32-41-03, Revision#: 40, Revision Date: 11/1/2020 ORIGINAL Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature:  14c. Approval/Certificate No.: 77AR783B	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): WELCEMEN B. JEANNOT 14e. Date (dd/mm/yyyy): 07-Aug-2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Work Order**Work Order #: 59105**

Date Printed: 8/7/2023

Time: 2:06:20 PM

Page: 1

To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: T41753

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 274N1051-3

Descr: BRAKE VALVE ASSEMBLY

Qty: 1

Station: HYDRAULIC

Make:

Model:

Mfg: _

Repair Manual(s): 32-41-03 Rev: 40 Rev. Date: 11/1/2020

Entry Date: 7/26/2023

Need Date: 8/11/2023

Compl. Date: 8/7/2023 2:03:

Warranty: No

Container:

Serial Numbers:

01975

RECEIVING INSPECTION

P/N and S/N verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

PRELIMINARY INSPECTION

P/N 274N1051-3 verified IAW technical data referenced above.

S/N 01975 verified through ID plate and customer RO.

No AD's applicable at this shop visit.

TSN: UNK

CSN: UN

TSO: UNK

CSO: UNK.

HIDDEN DAMAGE

None noted.

INITIAL FINDINGS

Unit failed IAW technical data referenced above.

Reason: External and internal leakage

Customer Complaint: None report.

Tech: RE. #129.

TEARDOWN FINDINGS

Unit disassembled, cleaned and inspected IAW technical data referenced above. Requires Replacement of all packings, seals and retainers removed during disassembly. NDT is required. Minor nicks, scratches, and dents do not affect fit, form, or function of the unit.

Unit will be overhauled.

Tech: RE. #129

CORRECTIVE ACTION

All parts listed in Teardown Report were replaced and findings listed were corrected. Unit was overhauled and tested IAW technical data reference above.

Tech: RR#127

Authorized Signature: _____

Name: WELCEMEN JEANNOT

Date: 8/7/2023



Aero Accessories & Repair, Inc.

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Packing Slip



SH39973

Aero Accessories & Repair, Inc.

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Customer: AJW AVIATION LTD.

Shipping Order: SH39973

Order: 59105

Terms: Not determined

Ship Via: FEDEX INTERNATIONAL PRIORITY

Ship Via Acc: 248185260

AWB: 635789716562

Page: 1

Date: 8/7/2023

Time: 4:10:23 PM

Ship To: AJW AVIATION LTD.

THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Customer PO#: T41753

Order Total: 0

Item	Part Number/Description	Serial Number	Qty	CD
	274N1051-3 BRAKE VALVE ASSEMBLY	01975	1	OH