

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 178892-1	
4. Organization Name and Address: SOUTHERN AEROPARTNERS, INC. D/B/A/ 4157 SOUTHWEST BLVD TULSA, OK. 74107 US				5. Work Order, Contract or Invoice Number: Work Order No.: SHY107334 Customer RO.: R414500	
6. Item		7. Description:		11. Status/Work:	
1		PRIMARY DOOR LOCK		TESTED	
12. REMARKS					
IN ACCORDANCE WITH CMM. 78-32-17 REV. 2 DATE: 07-JUN-2007					
NO APPLICABLE AD'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14c. Approval/Certificate No: QAKR523K	
13b. Authorized Signature:		13c. Approval/Authorization No:		14b. Authorized Signature: 	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): SAMANTHA TALLY	
				14e. Date (dd/mm/yyyy): 11/Aug/2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Southern Aeropartners, Inc. D/B/A		Tear Down/Inspection
4157 Southwest Blvd Tulsa, OK. 74107 US		
		Work Order #: SHY107334
		Date Printed: 11-Aug-23
		Page: 1 of 1

To: AJ WALTER *** THE HEADQUARTERS MAYDWELL AVENUE, SLINFOLD WEST SUSSEX RH13 0AS UNITED KINGDOM	Ship To: AJ WALTER *** LOGISTICS CENTRE THE BUSINESS PARK MAYDWELL AVENUE SLINFOLD, RH13 UNITED KINGDOM
--	---

Cust.PO Ref.:R414500	Cust.Phone: 44 1 40 371 1777	Cust.Email: projectsgroup@ajw-aviation.com
Cust.Code:310222	Cust.Fax: 1-441403710936	Station: SAI
IN. PN: TY1917-20B	Descr: PRIMARY DOOR LOCK	Qty: 1
OUT PN: TY1917-20B		

Serial Numbers: 20257

Faults:

*****SHOP REPORT*****

TECHNICIAN / NUMBER / DATE: J McGrail 109953 08-08-2023

P/N & SN ON DATA PLATE MATCHES PO/RO/WO: yes

REASON FOR REMOVAL: test

TEAR DOWN FINDINGS: Passed all testing.

NOTES:

RECOMMENDED WORK SCOPE: "TEST/INSPECT"

Corrective Actions:

"TESTED/INSPECTED" J McGrail 08-10-2023

CMM: 78-32-17 Rev: 2 Date: 07-Jun-2007