


1. Approving Civil Aviation Authority/Country Transport Canada		2.			AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking Number. WO146575			
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada										5. Work Order, Contract or Invoice Number: T41828	
6. Item:		7. Description:		8. Part Number:		9. Quantity:		10. Serial/Batch Number:		11. Status/Work:	
1		TRANSMITTER-LIQUID LEVEL		G540DA74		1.00		3783		INSPECTED/TESTED	
12. REMARKS INSPECTED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 38-32-53 Rev. 5 dated Jan 10/2019. FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN / INSPECTION REPORT.											
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12											
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17											
14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12											
13b. Signature:		13c. Approved Organization Number		14b. Signature 		14c. Approval Organization Number 33-12					
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Vincent Crete		14e. Date (dd/mm/yyyy) 21/Sep/2023					
Installer Responsibilities											
This certificate does not constitute authority to install the part.											
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.											

Work Order: WO146575

Date Printed: 9/21/2023

Customer RO: T41828

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: TRANSMITTER-LIQUID LEVEL

Phone:

P/N: G540DA74

Qty: 1

Email:

S/N: 3783

Mfg: DIEHL

TSN: UNK

TSO: UNK

TSR: UNK

CSN: UNK

CSO: UNK

CSR: UNK

P/N Out: G540DA74

S/N Out: 3783

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: Removed serviceable for test and certification

Faults:

CODE: NO FAULT FOUND

DETAILS: No faults were found during the initial test.

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is confirmed.

CODE: TEST ONLY

DETAILS: Unit was tested with no anomalies found during evaluation.

CODE: TEST AND RECERTIFY

DETAILS: Unit has been tested serviceable in accordance with CMM 38-32-53 Rev. 5 dated Jan 10/2019.

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: Unit has been tested serviceable in accordance with CMM 38-32-53 Rev. 5 dated Jan 10/2019.