


1. Approving Civil Aviation Authority/ Country: FAA/United States		2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: R376714	
4. Organization Name and Address: AOG Accessories 2549 N.W. 74th Ave. Miami FL 33122 USA Phone: 305-591-1899 Fax: 305-489-0176 FAA APPROVED REPAIR STATION NO. XB4R642M * EASA 145.5924				5. Work Order/Contract/ Invoice Number: 20183	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	GEARED ROTARY ACTUAT	755299D	1ea.	A8193	REPAIRED
12. Remarks: REPAIRED in accordance with CMM 27-81-32 Revision 24 Dated 2/16/2016 Full details of work carried out per work order no. 20183 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the GEARED ROTARY ACTUAT is considered ready for release to service under EASA Part 145 approval no. EASA 145.5924. EASA A.D.: No AD required. EASA S.B.: No SB required. FAA A.D.: No AD required.: FAA S.B.: No SB required.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Approval/Certificate No.: XB4R642M	
13b. Authorized Signature: Not Applicable	13c. Approval/Authorization No.: Not Applicable	14b. Authorized Signature: 		14c. Approval/Certificate No.: XB4R642M	
13d. Name (Typed or Printed): Not Applicable	13c. Date (dd/mm/yyyy): Not Applicable	14d. Name (Typed or Printed): Ray Disla		14e Date (dd/mm/yyyy): 22/Jul/2020	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

AOG Accessories

2549 N.W. 74th Ave.

Miami FL 33122

USA

Phone: 305-591-1899 Fax: 305-489-0176

C.R.S. No.: XB4R642M

Work Order: 20183

Date: July/22/2020

Page 1 of 1

Sold To:

AJ WALTER AVIATION, LTD

THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS

WEST SUSSEX UNITED KINGDOM

Ship To:

AJ WALTER AVIATION, LTD

THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS

WEST SUSSEX UNITED KINGDOM

Part Number: 755299D

Serial: A8193

Manufacturer: UTC AEROSPACE

Description: GEARED ROTARY ACTUAT

Model: 755299D

Purchase Order: R376714

Service Performed: REPAIRED

Data used: Manual Number: 27-81-32 Revision: 24 Date: 2/16/2016

Teardown/Inspection Data

1.- Trouble Reported: SHOP RESTORATION

Inst.: Repair Only.

Appearance: Normal

Corrosion: No Corrosion Noted.

Loose or Missing Parts: No Loose or Missing Parts.

Physical Damage: No damage found.

2. Teardown

Dissassembly: Only as Required for Repair.

Painting: None Performed.

Cleaning: Performed cleaning as required

Assembly: As Required

3. Test

Operation: TESTED I/A/W Mfg. Specs.

Was Complaint Verified: Yes

Modifications: NONE

Other problems found: None found.

4. Final

Warranty Accepted: N/A

Final Test and Inspection:

Final Inspection Normal.

FAA A.D.: No AD required.

FAA S.B.: No SB required.

EASA A.D.: No AD required.

EASA S.B.: No SB required.

5. Work Performed: LRU WAS DISASSEMBLED, CLEANED, INSPECTED AND REPAIRED. PERFORM RETURN TO SERVICE TEST, LRU MEETS MFGS SPECS AND IS READY FOR SERVICE.


Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Inspector's Name: Ray Disla

Order No.: 20183

Technician: Ricardo Mena

Signature: 

Date: July/22/2020

Inspector

Form: AOG 103 Original 03/17/2014