


1. Approving Competent Authority/Country CAA/UK		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number ARC48950	
4. Organisation Name and Address  WAS (COMPONENTS) LTD North Hangar Aviation Way Southend-on-Sea Essex SS2 6UN United Kingdom Tel: +44(0)1702 348601 Fax: +44(0)1702 541534 Email: Web:		5. Work Order/Contract/Invoice R356977			
6. Item 1	7. Description VALVE, WATER	8. Part No. WV9940-00	9. Qty. 1	10. Serial No. 00110114	11. Status/Work INSPECTED/TESTED
12. Remarks - WP66483 - INSPECTED & TESTED IAW A.O.A. C.M.M. REF. 38-32-60, REV. 2 DATED 14 JUN 2004 - TCCA No. : 816-06 -					
Return to Service in accordance with FAR 43.9. Certificate No: EGWY725K Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Title 14, Code of Federal Aviation Regulations, part 43 and in respect to that work, the items are approved for return to service. Pertinent details of the repair are on file at this repair station under order: No: R356977 Sign:  Date: APR 25 2019					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in block 12					
13b. Authorised Signature		13c. Approval/Authorisation Number		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature 	
14c. Certificate/Approval Ref. No. UK.145.00579		14d. Name - N STREET		14e. Date (dd mmm yyyy) 25 Apr 2019	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Inflite MRO Services Ltd
North Hangar
Aviation Way
Southend-on-Sea
Essex
SS2 6UN
United Kingdom
Tel: +44(0)1702 348601

WAS (COMPONENTS) LTD: EASA Part 145: UK.145.00579:

WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:

Workshop Report

No: **IR67093**

Issue: **01**

Date: **12-Apr-19**

A J Walter (Aviation) Limited
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0SH
United Kingdom

Attn: Miss Danielle Dinnage

Tel: 01403 798649

Fax: 01403 712135

E-Mail: Danielle.Dinnage@ajw-group.com

Your Ref: R356977

Our Ref No: WP66483

Test Required: N/A

Part No: WV9940-00

Description: VALVE, WATER

Serial No: 00110114

Workscope: Inspect & Test

Dept: Environmental Works Release Type: Dual

Removed From:

Serial No:

Reg No:

Position:

Workscope Overview:

PLEASE TEST UNDER T&M - QUOTE AND HOLD

Inspection Findings:

unit received in for test.

Unit inspected and test as per cmm and passed.

Inspected and tested iaw A.O.A. cmm 38-32-60, rev 2, dated 14/06/2004.

Signed:

Name:

N STREET

Date: **25 APR/2019**

For and on the behalf of Inflite MRO Services Ltd

Registered address:- Inflite House, Stansted Airport, Stansted, Essex, CM24 1RY