

1. Approving Civil Aviation
Authority/Country:
FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

R303219

4. Organization Name and Address:

SECURAPLANE TECHNOLOGIES, 12350 N VISTOSO PARK RD, ORO VALLEY, AZ 85755 SR0R383N

5. Work Order/Contract/Invoice Number:

RMA-067694

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	TAXI CAMERA INTERFACE UNIT	701435-500	1	701435-05070106	REPAIRED

12. Remarks: This document constitutes a signed copy of the work order.

CUSTOMER: AJW AVIATION LTD

CORRECTIVE ACTION: The above referenced unit has been repair and inspected in accordance with manufacturer's manual # MM-0231-01 Rev- (31-61-20) dated 4/27/2011 and tested to Acceptance Test Procedure (ATP) # AT702773 Rev C, dated 02-16-06.
Unit has passed all requirements.

Securaplane certifies the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.5074

The above referenced unit(s) is manufactured under FAA/PMA authority and has been tested in accordance with Securaplane Acceptance Test Procedure and has passed all requirements AIRWORTHINESS APPROVAL- PARTS.

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (m/d/y):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

Michael Caruth

01/NOV/2016

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

12350 N. Vistoso Park Rd. * Oro Valley, AZ 85755
(520) 297-0844 * (520) 425-8257 FAX

WORK ORDER

DATE LOGGED IN:

REQUIRED

RETURN DATE:

DOM: 08/2005

RMA-067694

DATE REC'D:

10/17/2016

10/31/2016

W/IN WARR

PERIOD: YES

PART NUMBER:

701435-500

PART NAME:

TAXI CAMERA INTERFACE UNIT

PART SERIAL NO.:

701435-05070106

AS RECEIVED

MOD NO: 4

SCN: N/A

CUSTOMER:

AJW AVIATION LTD

A/C OPR CODE: ZZZZZ

A/C #:

A/C TYPE: B777

LAST DATE

IN: 9/24/14

PREVIOUS RETURNS: 3

I CATEGORY:

REPAIR

*** PREPAYMENT REQUIRED ***

CUSTOMER REASON FOR RETURN:

REPAIR

COMPONENT MAINTENANCE SPECIFICATION / REV

MIM-0231-01

Rev. 1

ENG ORDER:

NONE

REV DATE:

RECEIVING INSPECTION

(PHYSICAL CONDITION):

YES NO

SEC. LABEL

☐ ☒

UNIT PROTECTED

☒ ☐

OTHER DAMAGE

☐ ☒

RECV INSPECTION NOTES:

INITIAL:

[Signature]

DATE: 10/17/16

INITIAL FINDINGS:

MODIFICATION

NO FAULT FOUND

INDUCED FAILURE

CONFIRMED

☐

☐

☐

☒

C-MFD intermittent

OCV

V/BATT1

V/BATT2

☐ BATTERIES ARE GREATER THAN 3 YEARS OLD.

REPLACEMENT PER CMM IS RECOMMENDED.

INITIAL: H.N.

BATTERY

DATE OF MFG

DATE:

OCT 24 2016

SERIAL

NUMBER

CAUSE OF RETURN / FAILURE ANALYSIS SUMMARY:

Replaced u4. Tested and recertified.

HARDWARE FAILURE

SOFTWARE FAILURE

☒

☐

ENG. CONCURRENCE:

[Signature]

DATE: 10/31/16

INITIAL: H. NGUYEN

DATE:

10/31/16

IV REWORK / CORRECTIVE ACTION:

*** SEE ATTACHED: DRR ***

UNIT COMPLETION

☐ BATTERY REPLACEMENT STICKER
PUT ON UNIT

OUTGOING MOD NO:

4

LAST REBLOCK DATE:

ATP: AT702773

REV: C

TEST TECHNICIAN: H. NGUYEN

DATE:

Oct. 31. 2016

FINAL INSPECTOR:

[Stamp]

DATE: NOV 01 2016

(INSPECTOR'S STAMP)

VI WARRANTY ACCEPTED:

NO

YES

TEST TECHNICIAN:

[Stamp]

Hung Nguyen

WORK ORDER VERIFICATION & 8130-3 SIGNEE:

DATE:

01 NOV 2016

COMPONENT MAINTENANCE SPECIFICATION CONFIRMED BY 8130-3 SIGNEE:

DATE:

01 NOV 2016

INCOMING INSPECTION / ADD PARTS

FINAL INSPECTION



12350 North Vistoso Park Rd.
Oro Valley, Arizona 85755
CAGE Code: 0TMJ9
PH: (520) 297-0844 FAX: (520) 498-4924

Repair Station Discrepancy Rework Record

Customer: AJW

[illegible]

*Part Designator/Part Number, P.O. No. or S/N

**** May be N/A if same as operation**