

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO146433	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: W52679	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	COCKPIT VOICE RECORDER	2100-1020-02	1.00	000231488	INSPECTED/TESTED
12. REMARKS TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-70-04 REV 22 DATED 15MAY2023. FOR ADDITIONAL INFORMATION REFER TO TEARDOWN/INSPECTION REPORT. U.L.B.P/N DK120/90, S/N AT134149. U.L.B. EXPIRY DATE: MAY 2026					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12			EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17		
13b. Signature:			14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12		
13c. Approved Organization Number			14b. Signature		
13d. Name (Typed or Printed):			14c. Approval Organization Number 33-12		
13e. Date			14d. Name (Typed or Printed) Robert Milbers		
			14e. Date (dd/mm/yyyy) 14/Sep/2023		
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

Work Order: WO146433

Date Printed: 9/14/2023

Customer RO: W52679

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: COCKPIT VOICE RECORDER

Phone:

P/N: 2100-1020-02

Qty: 1

Email:

S/N: 000231488

Mfg: L-3 COMMUNICATIONS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 2100-1020-02

Serial Out: 000231488

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: CVR INOP.

CODE: MOD/AMENDMENT STATUS AR

DETAILS: AMENDMENT STATUS ON ARRIVAL: Hardware MOD DOT: 1 - 4, 11, 13, 15. Software MOD DOT: 1.

CODE: WARRANTY

DETAILS: Consider for warranty.

Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal as per repair order is not confirmed. Unit passed computer bench tests multiple times and Underwater Locator Beacon voltage and ping tests in accordance with CMM 23-70-04 REV 22 dated 15May2023.

CODE: WARRANTY REQUESTED

DETAILS: Warranty requested is: Denied. No fault found. Unit passed all tests.

CODE: TEST AND RECERTIFY

DETAILS: Final test required in accordance with CMM 23-70-04 REV 22 dated 15May2023.

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: Tested serviceable in accordance with CMM 23-70-04 REV 22 dated 15May2023.
U.L.B. P/N DK120/90, S/N AT134149.

U.L.B. EXPIRY DATE: MAY 2026