

1. Approving Civil Aviation Authority / Country: FAA/United States		2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag			3. Form Tracking Number: 107581	
4. Organization Name and Address: Sherwood Aviation 4690 NW 128TH Street Opa-Locka FL 33054-5130 Phone: 305-477-2994 Fax: 305-477-3367					5. Work Order/Contract/ Invoice Number: R134720	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	Solenoid Valve Assy	3876047-4	1ea.	440	Inspected	
12. Remarks: Inspected I/A/W Honeywell A.T.A.: 49-23-49, Rev. No.: 39 dated 9/2/2015. Full details of work carried out per W/O as specified in Block 3. See Teardown / Inspection Form for additional information. All personnel associated with the MAINTENANCE of this part/component met the requirement of CFR 121.377. Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the Solenoid Valve Assy is considered ready for release to service under EASA Part 145 a;proval no. EASA 145.4866 .						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.						
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12		
Not Applicable		Not Applicable		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature:		
Not Applicable		Not Applicable				
				14c. Approval/Certificate No.: OOWR599L		
				14d. Name (Typed or Printed): Ernesto A. Lopez		
				14e. Date (dd/mm/yyyy): 05/Nov/2015		
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



SHERWOODAVIATION.COM

PHONE NO: 305 477-2994 4690 N.W. 128TH ST
FAX NO: 305 477-3386 OPA LOCKA, FL 33054

Work Order: 107581
Date: November/5/2015
Phone: 305-477-2994
Fax: 305-477-3367

TearDown/Inspection Form

Sold To:
Unical Aviation Inc
680 South Lemon City Of Industry, CA 91789

Ship To:
UNICAL AVIATION.
680 S. LEMON AVE. CITY OF INDUSTRIY, CA 91789

Part Number: 3876047-4 Serial: 440 Manufacturer: Honeywell
Description: Solenoid Valve Assy Model: GTCP331-200 Series A/C: Unknown
Purchase Order: R134720 Service Performed: Inspected
Data used: Manual Number: 49-23-49.

Teardown/Inspection Data

1.- Reason for Removal: Unknown Inst.: Unit to be Bench Checked and Inspect i/a/w mfg. spec

2. Initial Inspection Findings

Appearance: Normal Corrosion: No corrosion noted
Loose or Missing Parts: No loose or missing parts Physical Damage: No damaged found

3. Teardown

Disassembly: None Cleaning: None
Painting: None Assembly: None

4. Test

Operation: Tested I.A.W. MFG Specs Was Complaint Verified: N/A
Modifications: None

5. Final

Warranty Accepted: N/A Final Test and Inspection: Final inspection normal
T.S.O.: N/A A.T.A.: 49-23-49 A.D. S.B. NO A.D. / S. B. REQUIRED

6. Work Performed: Unit was tested and inspected IAW ATA 49-23-49. Unit passed functional test; no defects noted.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 107581

Inspector's Name: Ernesto A. Lopez
Certificate No. 2623565

Technician: Brendan Taylor

Signature: 

Date: November/05/2015

Form CRS-3