


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 194846 CTLID 1	
4. Organization Name and Address: BP Aero Services 4965 HANSON DR. IRVING, TX 75038 USA Ph: 469-208-0060, Fax: 972-252-2009 FAA Approval Holder: 442R874B				5. Work Order/Contract/Invoice Number: 85581 Number of attached pages - 1	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	PANEL, ASSY-ACOUSTICAL AFT	338-068-411-0	4	N/A	OVERHAULED
12. Remarks: ATA: 72-23-08 E.S.N. 779634 Repair Order: ERO17461 Customer: AJ Walter Aviation Ltd See Workscope Report : 85581 All work performed in accordance with CFM56-5B Manual ID: CFM1-TP-SM.9, Revision #: 78, Revision Date: 3/15/2022					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to Service under EASA Part 145 Approval Number: EASA.145.6427					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature: 		14c. Approval/Certificate No.: 442R874B	
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Mussie Dair		14e. Date (dd/mm/yyyy): 30-Dec-2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.					
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.					
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1 国家 Country P.R. CHINA	2. 中国民用航空总局 C.A.A.C. ☐ 符合性 Conformity	☒ 适航性 Airworthiness	3 证书编号 Certificate Ref. No. 78883			
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		5 工作单/合同单/发票 Work Order / Contract / Invoice 85581 Number of attached pages - 1				
4 单位 BP Aero Services FAA Repair Station # 442R874B 4965 HANSON DR. IRVING, TX 75038 USA Tel: 972-252-2800, Fax: 972-252-2009						
6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
1	PANEL, ASSY-ACOUSTICAL AFT	338-068-411-0	CFM56-5B	4	N/A	OVERHAULED
13 备注 Remarks ATA: 72-23-08 E.S.N. 779634 Repair Order: ERO17461 Customer: AJ Walter Aviation Ltd See Workscope Report : 85581 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 78, Revision Date: 3/15/2022						
14 新产品 New Parts 兹声明上述产品除第13项的其他规定以外，以按照上述国家适航条例进行制造、检验，并且该产 品（出口产品）符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above, except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15 使用过的产品 Used Parts 兹声明上述产品除第13项的其他规定以外，已按照上述国家适航条例和进口国提出的特殊要求 进行了工作。该产出品于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)				
16 批准人签名 Signature		18 批准日期 Date		19 中国民航总局授权 Issued by or on behalf of the CAAC F00100709		
17 批准人姓名 (打印的) Name (Printed)		Mussie Dair				

Workscope Report

Work Order #: 85581

Date Printed: 12/30/2022

Time: 6:38:46 PM

Page: 1

BPAERO SERVICES
4961 HANSON DRIVE IRVING, TX 75038 972-252-2800 WWW.BPAERO.COM
FAA REPAIR STATION #442R874B



To: AJ Walter Aviation Ltd THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM		Ship To: Repairs Group THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM	
Ref #: ERO17461	Phone #: +44 1403 711 777	Fax #: +44 1403 710 936	Email: stockmarket@ajw-aviation.com
Code: 12	Site: AWAL	PN: 338-068-411-0	Descr: PANEL, ASSY-ACOUSTICAL AFT
Qty: 4	Station:	Make:	Model:
CFM56-5B			
ESN 779634	Warranty Request N/A		
CSN	Complies With		
Entry Date: 11/28/2022	Need Date: 12/8/2022	Compl. Date: 12/30/2022	Warranty: No
Container:		Container:	

Serial Numbers:

Inspection Findings:

Visual / Dimensional Findings

Defects in Protective Coating.

Erosion in area A.

Repairs Required;

Repair 002- Reconditioning of the Protective Coating by Anti Erosion Paint.

Repair 006- Erosion Repair by Epoxy Adhesive.

Corrective Actions:

Overhauled - 8130/CAAC Issued

Repairs Performed;

Repair 002- Reconditioning of the Protective Coating by Anti Erosion Paint.

Repair 006- Erosion Repair by Epoxy Adhesive.

Task Description

Seg

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete



MS

RECEIVING INSPECTION

CFM56-5B-ESM-TASK-72-23-08-100-001 - CLEANING

CFM56-5B-ESM-TASK-72-23-08-200-001 - INSPECTION

CFM56-5B-ESM-TASK-72-23-08-300-006 - REPAIR 006

CFM56-5B-ESM-TASK-72-23-08-300-002 - REPAIR 002

PHASE II FINAL INSPECTION

FINAL CLEANING AND CONDITIONING

FINAL INSPECTION