1 Country	2		3 Certificate Ref. No.
Germany		Luftfahrt-Bundesamt A Member of the JAA **JAA FORM ONE** Authorised Release Certificate	101K6TBV01

4 Organisation approved by the Luftfahrt-Bundesamt to issue this form		5 Work Order/Contract/Invoice
Lufthansa Technik	Lufthansa Technik AG Weg beim Jäger 193 P.O.Box 63 03 00 D-22313 Hamburg Federal Republic of Germany	60131810

6 Item	7 Description	8 Part No.	9 Eligibility (*)	10 Qty.	11 Serial-/Batch No.	12 Status/Work
01	DMU-DATA MANAGEMENT UNIT	967-0511-002	UNKNOWN	001	309	TESTED/INSP.

13 Remarks

TT	TSO	TSC	TSF	TC	CSO	Task perf.	ATA	Pack Code	Prod. Resp.	Workshop Station	Responsible Workshop
UNKNOWN	UNKNOWN	N/A	000000	UNKNOWN	UNKNOWN	F	3136	00		224 /305	139233

TASK PERFORMED IN ACCORDANCE WITH CMM 31-36-01 REV 01 /CMDS REV 01

Abbreviations see over

CUSTOMER ORDER NO.: 29262

CUSTOMER: A.J. WALTER AVIATION LTD.

This civil aeronautical product has been maintained, altered, or modified (as appropriate) in accordance with U.S. Federal Aviation Regulations.

For Lufthansa Technik AG, HAMBURG,GERMANY

Cert. No. DLAY225D

Note: In the statement in block No. 19 indicating "other regulation specified in block 13" is checked, the above statement is not crossed out and block No. 20 of this JAA Form One is signed, this signature constitutes approval for return to service with respect to the work performed (see FAA AC 145-7).

Limited life parts will normally be accompanied by maintenance history including life used. For storage conditions see CMM or operator's maintenance program.

[X] Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.

14	19
[ ] Airworthiness [ ] Conformity only Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the applicable design data and with the airworthiness regulations of the stated country. (See over)	[X] JAR-145.50 Release to Service [X] other Regulation specified in block 13 Certifies that the work specified above except as otherwise specified in block 13 was carried out in accordance with JAR-145 and in respect to that work, the part(s) is (are) considered ready for release to service. (See over)

15 Signature	16 Approval Reference Number	20 Signature	21 Approval Reference Number
	LBA.G.0047		LBA.0001
17 Name	**18 Date (d/m/y)**	**22 Name** 022440 VANSELOW	**23 Date (d/m/y)** 07/12/2001

(*) Installer must cross-check eligibility with applicable technical data

TAG-No 60131810

Workshop Report

Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
P.O.Box 63 03 00
D-22313 Hamburg
Federal Republic of Germany

Customer Order No.: 29262	Certificate Ref. No.: 101K6TBV01
Customer: A.J. WALTER AVIATION LTD.	Work Order/Contract/Invoice: 60131810
Part No. as received: 967-0511-002	Serial No. as received: 309
Part No. as dispatched: 967-0511-002	Serial No. as dispatched: 309
	Description: DMU-DATA MANAGEMENT UNIT
	Responsible Workshop: 139233

Reason for Removal: AIRCRAFT WAS SUBJECT TO CHEMICAL SPILLAGE IN THE REAR CARGO HOLD.

Findings: NO FINDINGS.

Action:

VISIUAL CHECK AND COMPLETE TEST.
LOADED SOFTWARE: P/N SE1N03
P/N VN1003C00000

Modification Status as dispatched according to Mod-Label: HW1

Signature: Vanselow

Name: 022440 VANSELOW

Date (d/m/y): 07/12/2001

The work specified above has been performed subject to Lufthansa Technik's Standard Conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

LHT Form 30992 A-98 (HAM WG) Printed in the Federal Republic of Germany