

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: R339218	
4. Organization Name and Address: JJA AVIATION INC. 3468 W 84TH ST BAY.106, HIALEAH FL 33018, (305)498-7920, (786)558-462				5. Work Order/Contract/Invoice Number: 10299	
6.Item:	7. Description:	8. Part Number:	9. Quantity:	10.Serial/Batch Number:	11. Status/Work:
1	PRINTED WIRE ASSY	285A1780-5	1	D00125	REPAIRED
12. Remarks: REPAIRED IN ACCORDANCE WITH CMM 23-42-10 REV.29 DATED SEP 30,2016 FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NO. : 10299					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA 145 and with respect to that work the aircraft component is considered ready to release to service under EASA Acceptance Certificate Number: 145.5947					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Authorized Signature: 	
13b. Authorized Signature:		13c. Approval/Authorization No.:		14c. Approval/Certificate No.: J30R252Y	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14d. Name: (Typed or Printed) JUAN C ALEMAN	
				14e. Date (dd/mm/yyyy): 25 / Jun / 2018	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14)					
NSN: 0052-00-012-9005					



WORK ORDER

JJA AVIATION INC.

3468 W 84TH ST BAY.106

HIALEAH FL 33018

Fax: (786)558-462

(305)498-7920

Supporting your Goals FAA CRS No : J30R252 / EASA.145.5947

Page No. 1



WO: 10299-18

Customer : AJW001 / AJ WALTER AVIATION LTD

Outg. P/N : 285A1780-5 / PRINTED WIRE ASSY

Manufact.: BAE

Dept.: ACC

Cust RO : R339218

Outg. S/N : D00125

Warranty : 00 / 365

Goodthru AD# :

Manual#: MN-0589 ATA: 23-42-10 Rev#: 29 RevDate: Sep 30, 2016 Revised Date: May 9, 2018

Assets: A-0088, A-0162, H-0335, A-0585, A-0528, A-0525, A-0075, A-0151, A-0532, A-0652, A-

Incoming P/N: 285A1780-5

Incoming S/N: D00125

Incoming Work Req:

Work Performed: REPAIR

Reason/Rm:

BROKEN PIN ON A CONNECTOR

Date Recvd: May 9, 2018

Date Reqr: Jun 30, 2018

Date Estmtd: May 14, 2018

PRELIMINARY INSPECTION:

DATE: May 15, 2018

INSPECTOR: LEG

VERIFIED PART NUMBER AND SERIAL NUMBER.

UNIT RECEIVED IN FAIR CONDITION.

PRE TEST (Yes/No): Y

DATE: May 15, 2018

INSPECTOR: LEG

UNIT FAILED FUNCTIONAL TEST.

VERIFIED TROUBLE REPORTED.

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

OPENED UNIT AS REQUIRED FOR INSPECTION AND TROUBLESHOOTING. INSPECTION REVEALED BROKEN PIN E27 ON CONNECTOR J7 AND DEFECTIVE RESISTOR R122.

UNIT REQUIRES CLEANING AND REPAIR.

LEAD TIME AFTER APPROVAL 39 DAYS

TECHNICIAN: EXV

DATE: May 15, 2018 INSPECTOR: LEG

FINAL INSPECTION BEFORE ASSEMBLY:

DATE: Jun 25, 2018 INSPECTOR: JCA

CORRECTIVE ACTION:

CLEANED, INSPECTED, REPLACED DEFECTIVE PARTS MENTIONED ON TEARDOWN FINDINGS, REASSEMBLED, REPAIRED AND FUNCTIONALLY TESTED UNIT I/A/W MFG SPEC'S.

TECHNICIAN: EXV

DATE: Jun 25, 2018 INSPECTOR: JCA

MODIFICATION/SERVICE BULLETINS:

NO S/B INSTALLED AND N/A AD'S.

Test Data Used: ATA# 23-42-10 REV# 29 DATED: 09-30-2016

Test Technician: EXV

DATE: Jun 25, 2018

Inspector: JCA

DATE: Jun 25, 2018

Final Inspection: JCA

DATE: Jun 25, 2018

Labor Task Control#





WORK ORDER

JJA AVIATION INC.

3468 W 84TH ST BAY.106

HIALEAH FL 33018

Fax: (786)558-462

(305)498-7920

Supporting your Goals FAA CRS No :J30R252 / EASA.145.5947

Page No. 2



WO: 10299-18

Customer : AJW001 / AJ WALTER AVIATION LTD

Outg. P/N : 285A1780-5 / PRINTED WIRE ASSY

Manufact.: BAE

Dept. : ACC

Cust RO : R339218

Outg. S/N : D00125

Warranty : 00 / 365

Goodthru AD# :

ADDITIONAL COMMENTS:

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved return to Service By JUAN C ALEMAN

Date Jun 25,2018

Labor Task Control#

