

1. Approving competent Authority / Country Luftfahrt-Bundesamt/ Germany		2.		3. Form Tracking Number 2001238330	
4. Organisation Name and Address LIEBHERR-AEROSPACE LINDENBERG GmbH • Pfaffenstr. 50-52 - 88161 • Lindenberg • Germany • Phone: +49 (0) (8381) 46-0 • Fax: +49 (0) (8381) 46 4377				5. Work Order / Contract / Invoice 2001238330	
6. Item		7. Description		8. Part No	
1		VALVE BLOCK, ASSY		787A0000-08	
9. Qty.		10. Serial No		11. Status / Work	
1		0787A00LI032512		Repaired	
12. Remarks Approved Data: 27-09-22 / Rev. 10 / 26.10.2018 SFR No.: 13022 Rev.3 DMF: 062015					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non approved design data specified in block 12.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. ☒ Part-145 A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature ANDREAS BAYER Electronic Signature on File	
				14c. Certificate / Approval Ref. No DE:145.00034	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Andreas Bayer	
				14e. Date (dd mmm yyyy) 14. Dec. 2020	
14. Certificates that the work specified in block 11/12 was carried out in accordance with FAR Part 43 and in respect to that work the part(s) is (are) approved for return to service. Pertinent details of the repair are on file at the repair station under Order No. (see block 5). Date: 14/12/2020 Signed: ANDREAS BAYER For LIEBHERR-AEROSPACE, Cert. No. LA7Y195J TCCA acceptance number: 898-09					

User / Installer Responsibilities
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.
EASA Form 1-21 Issue 2 / - MF/CAO/145 Issue 3.

SHOP FINDING REPORT

LIEBHERR REPAIR DOSSIER:	13022	CONTACT:	ccca3 lli
RECEPTION DATE:	10 NOV 2020	EMAIL:	ccca3.lli@liebherr.com
CUSTOMER PURCHASE ORDER:	R378829	DATE:	14 DEC 2020
OPERATOR:	Viva Aerobus		
AIRCRAFT TYPE:	A320		
AIRCRAFT REG. NUMBER:	XA-VAN		
AIRCRAFT SERIAL NUMBER:	N/A		
ADD. CUSTOMER DOCUMENTS:	N/A		

RECEIVED UNIT

CUSTOMER REFERENCE: 787A0000-08
PART NUMBER: 787A0000-08
AMENDMENT: -
SERIAL NUMBER: 0787A00LI032512
DESCRIPTION: VALVE BLOCK, ASSY
CONCESSION: N/A
MANUFACTURING CODE : D9893
MANUFACTURING DATE : 062015

DELIVERED UNIT

CUSTOMER REFERENCE: 787A0000-08
PART NUMBER: 787A0000-08
AMENDMENT: -
SERIAL NUMBER: 0787A00LI032512
DESCRIPTION: VALVE BLOCK, ASSY
CONCESSION: N/A

TIMES & CYCLES

TSN	TSO	TSI	CSN	CSO	CSI
N/A	N/A	N/A	N/A	N/A	N/A

INSTALLATION DATE:	N/A	REMOVAL DATE:	N/A
LOG CARD EXISTING:	No	LOG CARD (Copy/Orig.):	No
LIFE LIMITED PARTS:	No	NON INCIDENT STATEM.:	No

MAINTENANCE DOSSIER: 787* / VERSION 1 (09 SEPT 2020)
APPROVED DATA & MAINTENANCE DOCUMENTS: CMM 27-09-22 / REVISION 10 / 26 OCT 2018

TYPE OF CERTIFICATE:	FAA PART 145, TCCA PART 145, EASA PART 145	WORK REQUESTED:	Repair
		WORK PERFORMED:	Repaired

REASON FOR RETURN:

F/CTL Flap Sys 2 fault

FINDINGS AND ANALYSIS:

Findings from Analysis:

- Reason for return not confirmed
- No failure found - Unit was incorrectly disassembled, L-787-SB-0001_787A-27-05 not required. (Fundamental Finding)

WORK PERFORMED:

- Unit partially disassembled in accordance with the referenced approved data.
- Unit cleaned in accordance with the referenced approved data.
- Unit inspected in accordance with referenced approved data.
- Unit repaired in accordance with the referenced approved data.
- Unit tested in accordance with referenced approved data.
- SIL230 performed.

LIFE LIMITED PARTS RECEIVED:

N/A

LIFE LIMITED PARTS DELIVERED:

N/A

SHOP FINDING REPORT APPROVED:

VALIDATION DATE: 14 DEC 2020
VALIDATED BY: Kaspar Steinmaier (electronic signature)