1. Approving Civil Aviation 2.			AUTHORIZED RELE	3. Form Tracking Number:					
FAA/United States			FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			T17109			
	ration Name and Address:	\\+	Control of the contro			5. Work Order/Contract/Invoice Number:			
it is esse	onsi i i kasilan si i i	Air Transpore	900 N. Fiesta Blvd.	Z	Z6AR209Y				
12.0	**		Gilbert, AZ 85233			W0082060			
			480-831-1268 FAX	480-831-1314		VV0002000			
	-								
6. Item:	7. Description:		t Number:	9. Quanti					
1	MLG ACTUATOR ASSY	65-	44910-27	1	TSC2423	TESTED			
	, 2								
	5	an 1615°		1					
	*	1.0							
			9						
			. 143 /						
12. Remai			lanes-						
	TESTED UNIT IAW BOE	ING CMM 32-30-11,	REV #56 DATED NOV 01/12.						
			ECIFIED IN BLOCK 11/12 WAS CARR			RESPECT TO THAT			
•WORK TH	HE AIRCRAFT COMPONENT IS C	CONSIDERED READY FOR	RELEASE TO SERVICE UNDER EASA	APPROVAL CERTIFICATE N	O: EASA.145.5116."				
	ies the items identified above v		ormity to:	14a. ☑14 CFR 43.9 Seturn to Service ☑Other regulation specified in Block 12					
	ved design data and are in a со pproved design data specified н			Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in					
				respect to that work, the items are approved for return to service.					
13b. Auth	orized Signature;	13c. Approval	Authorization No:	14b. Authorized Signature		14c. Approval/Certificate No:			
				2. Parking		Z6AR209Y			
13d. Name (Typed or Printed): 13e. Da		13e. Date (dd)	mmm/yyyy):	14d. Name (Typed or Printed):		14e. Date (dd/mmm/yyyy):			
				TRENT DAWKINS		17/MAR/2014			
			User/Install	er Responsibilities	and the second s				
li .			one does not automatically constitute a	(C)	-				
			nal regulations of an airworthiness auth s authority accepts aircraft engine(s)/pro						
L + ' .			cation. In all cases, aircraft maintenance	1					
	nal regulations by the user/instal			4					

916



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268 FAA Repair Station # Z6AR209Y Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATIO Nomenclature MLG ACTUATOR ASSY Part Number 65-44910-27	MFG	TSC2423	CUST-PO:	# T17109	W0082060 737-SERIES
Reason For Removal/Customer Instru TEST AS REQUIRED IAW MFG SPECS. DUAL RELEASE REQUIRED. MIS-IDENTIFIED S/N TS02423 ON RO NOTIFICATION SENT 03/10/14 *AE*	ctions			-	ance
Visual Inspection Prior To Teardow NO VISUAL DEFECTS FOUND.	n:				
Preliminary Test Results: TESTED IAW CURRENT OEM/MFG SPECS ALL TESTS PASSED.					7.
Teardown And Inspection Findings: UNIT PASSED TEST NO DEFECTS FOUN	D.				
Corrective Action Taken: TESTED UNIT IAW BOEING CMM 32-30	-11, REV	#56 DATED N	OV 01/12		
Final Disposition: TESTED					
	ECTOR TD	TRENT DAWK	INS	DATE MA	AR/17/2014
For further info contact Poy	Hude	at 480-8	31-1268	FAX 480-	831-1314
/	/				ATC009



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268

FAA Repair Station # **Z6AR209Y** Fx: 480-831-1314

SHIPPER

Invoice#

0079934

Work Order# W0082060

Date Shipped 17 MAR 2014

Fed Ex#

124277507

CUST P/O#

24 3

T17109

10109

AJ WALTER AVIATION LTD.

THE HEADQUARTERS"

MAYDWELL AVENUE

WEST SUSSEX RH 13 OSH

UNITED KINGDOM

Ship To 10109

AJ WALTER AVIATION LTD.

THE HEADQUARTERS

MAYDWELL AVE

SLINFOLD, WEST SUSSEX,

RH 13 0AS

UNITED KINGDOM

P/O# T17109 Terms 2%/10 NET 3Via DHIANTERNATIONAAWB ______

Work Performed: TEST

Work Order# W0082060

1 ea 65-44910-27

Serial# TSC2423

MLG ACTUATOR ASSY

TESTED UNIT IAW BOEING CMM 32-30-11, REV #56 DATED NOV 01/12.

DHL #960301029.

PART NUMBER, SERIAL NUMBER AND MODE OF SHIPMENT IN REFERENCE TO THIS WORK ORDER HAVE BEEN CHECKED AGAINST THE ENCLOSED UNIT.

SIGNATURE:

SHIPPER ONLY, Invoice# 0079934 will follow.

900 N. Mario Berg FTA C CE , 100

-- bus 531-1-

Gilbert, AZ 8:

NST CSED WE'L'.T.

· 高/国对....

A COLUMN A FAM Repoir Sto

M. 电配电阻

100

SE ME THOTOSH



1.	AT	A SPEC 106 MATERIAL	CERTIF	FICATION	I FOR	M			
2. Seller's Name:				3. EX ESN					
	A J Walter Av	viation Ltd							
4. Orga	nization:		Phone#: +44 (0) 1403 711 777						
	A J Walter Aviation Ltd	Fax#: +44 (0) 1403 710 936							
,	Address:								
	The Headquarters Maydwell Avenue		SITA/Wire Code: LGWJWCR						
	West Sussex		Status: Distributor / Stockist						
	Slinfold, United Kingdom	RH13 0AS	Certificate Type and #: _						
5A. Sel	ler's Contract #:		5B. Buyer's PO #:						
6. Item	7. Description	8. Manufacturer & Part Number		9. Eligbility	I10 Oh	11. Serial/Batch #	12. Status		
	ACTUATOR ASSY-MAIN	65-44910-27		B737CL	10. Qty	SN: TSC2423	SV Status		
	GEAR	BOEING COMMERCIAL AIRCRAF	Т	Broroc		ON. 1002420	30		
						SA 1 **			
				, a.e.	31	d			
ď						,			
	12/12.	VIA CH	*			_ (%) _ s			
13A. Re TSN: The sup was (we	plied part(s) have not been so	CSN: (a) ubjected to severe stress or heat (as i Government or Military Source unles:	oplicable fo		cident or	fire) and			
	tained From:	Course unless		Certificated /	Janou				
	GENHEIM AVIATION PARTN	13C. Last Certificated Agency: AIR TRANSPORT COMPONENTS							
THE FOLL	Parts/Material Verification OWING SIGNATURE ATTESTS THAT DI ABOVE WAS (WERE) MANUFACTU PAH), OR TO AN INDUSTRY COMME	18. Used, Repaired or Overhaul Parts Verification: THE FOLLOWING SIGNATURE ATTESTS THAT THE DOCUMENTATION SPECIFIED ABOVE OR ATTACHED IS ACCURATE WITH REGARD TO THE ITEM(S) DESCRIBED.							
15. Sign	ature	19. Signature							
16. Nam	е	20. Name 21. Date 29/07/2014							

NOTICE: The above signature binds the seller and the SIGNER to the accuracy of the information provided in the FORM. Should the information provided in this Form contain inaccuracies or misrepresentations, the signer and SELLER may be liable for damages and be subject to criminal prosecution under state and federal law. AJW039/1

ERTH CATION FORM ATA SPECTION MATERIA 2 Select Vame: B EX ESN A J Walter Aviation Ltd :1490 for LLP's) - uppend part(s) have not been subjected to severe streas percent of chained from any US Government of Meta-