


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 312773	
4. Organization Name and Address:  AIRCO SERVICES AirCo Services, LLC 2995 Lone Oak Circle Suite# 10 Eagan, MN 55121 Ph: 316-945-9820, Fax: 316-945-8014 FAA Approval Holder: T12R188L		5. Work Order/Contract/Invoice Number: X379			
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	FLIGHT CONTROL MODULE	69-37313-401	1.00	D01638	INSPECTED/TESTED
12. Remarks: REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED I/AW, Manual ID: 31-36-81, Revision #: 44, Revision Date: 7/1/2017 MODS INSTALLED: NONE Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number. EASA.145.4100. 13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12 14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 13b. Authorized Signature: 13c. Approval Authorization No.: 13d. Name (Typed or Printed): 13e. Date (dd/mm/yyy): 14b. Authorized Signature:  14d. Name (Typed or Printed): Adam Holstine 14c. Approval/Certificate No.: T12R188L 14e. Date (dd/mm/yyy): 03-Mar-2022 User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14)					
NSN:0052-00-012-9005					

**AirCo Services, LLC**

2995 Lone Oak Circle

Suite# 10

Eagan, MN 55121

FAA REPAIR STATION #T12R188L

Tear Down/Inspection

Work Order #: X379

PN: 69-37313-401

Desc: FLIGHT CONTROL MODULE

SN: D01638

To:

ATTN: ELLIOT MITCHELL
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WE RH13 OSH
UNITED KINGDOM

Ship To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 OAS
UNITED KINGDOM

Date Printed	Cust No.	Terms	Customer Contact			Cust PO
3/3/2022	01489	N30	ELLIOT MITCHELL +44 1403 798752			R392179
F.O.B.	Ship Via		Manual:	Revision:	Rev Date:	Location:
	FEDX INT'L PRIORITY	248185260	31-36-81	44	7/1/2017	
ASSIGNED TECHNICIANS				ASSIGNED INSPECTOR		
Steve				Adam Holstine		

Action Requested

REPAIR

Sometimes YAW damper fail. Advise cost to Repair IAW mfg specs.

Faults:

INSPECT

Performed preliminary inspection and testing. Unit is working correctly. Unable to get YAW damper to fail. Unit requires a full functional test IAW mfg specs.

Action Taken:

INSPECTED/TESTED

Inspected IAW mfg specs. Bench checked and functionally tested unit IAW CMM 31-36-81, Rev 44, 07/01/2017. Tagged Unit Inspect/Tested and certified airworthy IAW mfg specs.

By:

Date:

03/03/2022