

1. Approving Civil Aviation
Authority/Country:

2.

FAA/United States

AUTHORIZED RELEASE CERTIFICATE
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

W28377719791

4. Organization Name and Address:

General MRO Aerospace

3018 NW 72nd Ave

MIAMI, FL 33122

Ph: 305-482-9903, Fax: 305-482-9905

sales@generalmroaerospace.com

FAA Approval Holder: 19GR994Y

5. Work Order, Contract or
Invoice Number:

R312520



6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 OUTFLOW VALVE

20792-02AC

1

0252014

REPAIRED

12. REMARKS:

Full details describing the actual work performed are contained and held in W/O # W28377.
This unit was REPAIRED in accordance with:

MFG: NORD-MICRO ATA Manual ID: 21-32-34, Revision #: 5, Revision Date: 11/29/2012

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.6095".

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No:

14b. Authorized Signature:

14c. Approval/Certificate No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

EDUARDO MORALES

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**General MRO Aerospace**

3018 NW 72nd Ave

MIAMI, FL 33122

Ph: 305-482-9903, Fax: 305-482-9905

sales@generalmroaerospace.com

Teardown**Work Order #: W28377**

Date Printed: 11/17/2017

Time: 3:04:05 PM

Page: 1

To:

AJW TECHNIQUE
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD, RH13 0AS
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD, RH13 0AS
UNITED KINGDOM

Ref #: R312520

Phone #: 514-339-5099

Fax #: 514-339-5099

Email: sales.inventory@ajw-technique.com

Code: 165

Site: YN2

PN: 20792-02AC

Descr: OUTFLOW VALVE

Qty: 1

Make:

Model:

Mfg: NORD-MICRO

Serial Number: 0252014

Entry Date: 2/20/2017

Need Date: 11/8/2017

Compl. Date: 11/16/2017 4:30

Warranty: No

Container:

ATA: 21-32-34 Loc: 3039 Revision: 5 Rev Date: 11/29/2012

REMARKS**SUBCOMPONENT PN AND SN**

ELECTRONIC BOX ASSEMBLY

P/N: 21071-02AC

S/N: 0255774

2) S/N: 0255773

BRUSHLESS MOTOR

P/N: 20781-02

S/N: 0244947

DC MOTOR ASSEMBLY

P/N: 20783-01

S/N: 0191144

GEAR BOX

P/N: 21029-01

S/N: 0252346

REASON FOR REMOVAL

CAB PR SYSTEM 1&2 FAULT

PRELIMINARY INSPECTION

P/N and S/N verified from RO and Unit.

PRE TEST (YES/NO)

Unit was tested and passed all functional tests

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
[X] Approved | Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

EDUARDO MORALES

Authorized Signature:

Date:

11/17/2017

Form created with Quantum Control(tm) technology. Product Licensed to: General MRO Aerospace

**General MRO Aerospace**

3018 NW 72nd Ave

MIAMI, FL 33122

Ph: 305-482-9903, Fax: 305-482-9905

sales@generalmroaerospace.com

Teardown**Work Order #: W28377**

Date Printed: 11/17/2017

Time: 3:04:06 PM

Page: 2

To:

AJW TECHNIQUE
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD, RH13 0AS
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS
UNITED KINGDOM

Ref #: R312520

Phone #: 514-339-5099

Fax #: 514-339-5099

Email: sales.inventory@ajw-technique.com

Code: 165

Site: YN2

PN: 20792-02AC

Descr: OUTFLOW VALVE

Qty: 1

Make:

Model:

Mfg: NORD-MICRO

Serial Number: 0252014

Entry Date: 2/20/2017

Need Date: 11/8/2017

Compl. Date: 11/16/2017 4:00

Warranty: No

Container:

ATA: 21-32-34 Loc: 3039 Revision: 5 Rev Date: 11/29/2012

HIDDEN DAMAGE

No Hidden Damage Reported.

TEARDOWN FINDINGS

During teardown inspection the following discrepancies were found:

Unit was cleaned, inspected and functionally tested. Unit passed all functional tests. Unit was disassembled for cleaning. Upon inspection found worn cables, corroded hardware and broken gate seal strip. Unit requires mentioned parts, paint and reconditioning for Repair.

Discrepancies Noted:

1. Worn cables - Requires Replacement
2. Hardware corroded - Requires Replacement
3. Broken gate seal strip - Requires Replacement

Rework Required:

1. Reconditioning
2. Paint

Repair Quote

Technician: R. Rodriguez

Inspector: H. Bembry

Date: 03/14/2017.

AD/SERVICE BULLETINS/MODIFICATIONS

No AD applicable to this component..

WORK PERFORMED

Replaced all mentioned parts. Performed cleaning, safety wire, paint and reconditioning. Unit was tested and passed all functional tests. Unit has been Repaired IAW NORD - MICRO CMM, ATA 21-32-34 Rev 5 DTD November 29, 2012.

Technician: J. A. Diaz

Inspector: R. S. Gonzalez

Date: 11/15/2017.

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
[X] Approved | [] Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

EDUARDO MORALES

Authorized Signature:

Date: 11/17/2017

Form created with Quantum Control(tm) technology. Product Licensed to: General MRO Aerospace