



61901967

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 21587262 00000001	
4. Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order/Contract/Invoice 61901967	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	ISOLATOR VIBRATION		1	227	REPAIRED
12. Remarks A.J. Walter (Aviation) Ltd. T39318 SAFETY SEAL NO: 90316180 INSTALLED. TP R MK-No. 20 Pack Code 00 Resp. Workshop 33362030 Workshop Station HAM063 Opr. Hours Cycle Opr. Day TT UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0 TASK PERFORMED IN ACCORDANCE WITH CMM 49-20-17 REV. 0 Return to Service in Accordance with 14 CFR part 43 The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under FAA Certificate No.: DLAY225D TCCA Approval No.: 897-08 ☒ Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents 14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service. 13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12 13b. Authorised Signature 13c. Approval / Authorisation Number 13d. Name 13e. Date (dd mm yyyy) 14b. Authorised Signature 027231 14c. Certificate / Approval Ref. Number DE.145.0001 14d. Name Rainer Jensen 14e. Date (dd mm yyyy) 18 Jul 2023					

EASA FORM 1 - Issue 3


USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LHT Form 30800 H-21 (HAM TQ A)



61901967

1. Approving Competent Authority / Country CAA UK		AUTHORISED RELEASE CERTIFICATE CAA FORM 1				3. Form Tracking Number 21587262 00000001	
4. Organisation Name and Address  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		5. Work Order / Contract / Invoice 61901967					
6. Item 01	7. Description ISOLATOR VIBRATION	8. Part No. 94830-11	9. Qty. 1	10. Serial No. 227	11. Status / Work REPAIRED		
12. Remarks ATA 4912 TP R MK-No. 20 Pack Code 00 Resp. Workshop 33362030 Workshop Station HAM063 SAFETY SEAL NO: 90316180 INSTALLED.							
A.J. Walter (Aviation) Ltd. T39318							
TT	Opr. Hours UNKNOWN	Cycle UNKNOWN	Opr. Day UNKNOWN				
TSC	UNKNOWN	UNKNOWN	UNKNOWN				
TSC	UNKNOWN	UNKNOWN	UNKNOWN				
TSF	0	0	0				
TASK PERFORMED IN ACCORDANCE WITH CMM 49-20-17 REV. 0							
☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.							
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12 ☐ Part -145.A.50 Release to Service ☐ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.							
13b. Authorised Signature		13c. Approval / Authorisation Number		14b. Authorised Signature 027231		14c. Certificate / Approval Ref. Number UK: 145.01408	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Rainer Jensen		14e. Date (dd mmm yyyy) 18 Jul 2023	

USER / INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

Customer Order No.	T 39318	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	61901967 Certificate Ref. No.	21587262 00000001	
Part No. as received	94830-11	Serial No. as received	227	Work Order/Contract/Invoice	61901967
Part No. as dispatched	94830-11	Serial No. as dispatched	227	Description	ISOLATOR VIBRATION
Reason for removal	PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS TEST. REMOVED IN SERVICEABLE CONDITION FROM NC REGN: VT-SCA THIS UNIT WILL BE COMING BACK INTO AJW STOCK AFTER REPAIR AVID RELEASE. I CAN CONFIRM THIS WILL NOT BE RELEASED TO ANY CURRENT SANCTIONED COUNTRY. IN ACCORDANCE WITH OUR STANDARD TERMS AND CONDITION. AVAILABLE O V THE IJWWEB SITE. SEE SECTION 14 IN OUR STANDARD TERMS AND CONDITIONS		Responsible Workshop	33362030	Modification Status according to Mod-Label
Findings	ISOLATOR ARRIVED IN CONTAMINATED CONDITION. DISASSEMBLY AND CLEANING FOR INSPECTION NECESSARY. MINOR SURFACE DEFECTS ON HOUSING; POLISHING AND PASSIVATING NECESSARY. MOLDED CORE DIMENSIONS OUT OF LIMIT; REPLACEMENT NECESSARY.MEASURED 39.38mm.CMM LIMIT IS 40.89mm. BOLTS CORRODED AND WASHERS WORN.		See Unit Mod-Label if equipped		
Action	ISOLATOR DISASSEMBLED AND ALL COMPONENTS CLEANED AND INSPECTED. HOUSING DIMENSIONAL INSPECTED ACC. TO CMM WITHOUT COMPLAINT. MINOR SURFACE DEFECTS ON HOUSING BY LOCAL POLISHING. MPI CHECK PERFORMED WITHOUT COMPLAINT. HOUSING PASSIVATED. BOLTS AND KEY WASHER REPLACED. NEW MOLDED CORE INSTALLED. ISOLATOR COMPLETED AND SEALED.		Name		
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.			27231, Rainer Jensen		
			Date (dd mmm yyy)		
			18 Jul 2023		