



1. Approving Competent Authority / Country

2

61397844

3. Form Tracking Number

LBA / Germany

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

19603805 00000001

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61397844

6. Item

8. Part No.

9. Qty.

10. Serial No.

11. Status / Work

7. Description

01 OUTBOARD OVERHEAD ELECTR UNIT

1167008-141

1

B-9104012628

REPAIRED

12. Remarks

A.J. Walter (Aviation) Ltd. R328487

ATA 2300

TP R

MK-No. 20

Pack Code 00

Resp. Workshop 32322012

Workshop Station FRA025

Opr. Hours UNKNOWN
Cycle UNKNOWN
Opr. Day UNKNOWN
TT UNKNOWN
TSC UNKNOWN
TSF UNKNOWN
0 0 0 0 0 0

TASK PERFORMED IN ACCORDANCE WITH CMM 23-35-08
REV 87 CMLS 23-35-08 ISSUE 020

FAA Certificate No. DLA7225D

TCCA Approval No. 897-08

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in a condition for safe operation
- ☐ non-approved design data specified in block 12

14a. ☒ Part-145 A.50 Release to Service

Certifies that, unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

☒ Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

446448

13d. Name

13e. Date (dd mm yyyy)

14d. Name

Florian Langer

14c. Certificate / Approval Ref. Number

DE.145.0001

14e. Date (dd mm yyyy)
02 Nov 2017

EASA FORM 1 - Issue 2 USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

61397844



1 国家 Country	2	3 证书编号 Certificate Ref. No.
--------------	---	-----------------------------

P. R. China

中国民用航空总局

CAAC

☐ 符合性 Conformity☒ 适航性 Airworthiness

批准放行证书/适航批准标签

LHT / CAAC / A /
19603805 00000001

Authorized Release Certificate / Airworthiness Approval Tag

4 单位 Organisation



Lufthansa Technik

5 工作单/合同单/货单
Work Order/Contract/InvoiceLufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

61397844

6 序号 Item

7 内容 Description

01 OUTBOARD OVERHEAD ELECTRIC UNIT

8 件号 Part No.

1167008-141

9 适用性 Eligibility

UNKNOWN

10 数量 Qty.

1

11 系列号/批号
Serial / Batch No.

B-9104012628

12 产品状态
Status / Work

REPAIRED

13 备注 Remarks

A.J. Walter (Aviation) Ltd. R328487

ATA 2300

TPR

MK-No. 20

Pack Code 00

Resp. Workshop 32322012

Workshop Station FRA025

Opr. Hours UNKNOWN Cycle UNKNOWN Opr. Day UNKNOWN
TSO UNKNOWN UNKNOWN UNKNOWN UNKNOWN
TSC UNKNOWN UNKNOWN UNKNOWN UNKNOWN
TSF 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 23-35-08
REV 8 / CMMDS 23-35-08 ISSUE 020

For storage conditions see CMM or Operator's maintenance program. Limited life parts will normally be accompanied by maintenance history including life used.

14. 新产品 New Parts

兹声明上述产品除第13项的其它规定以外,已按照上述国家适航条例进行制造/检查,并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。

Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured in accordance with the airworthiness regulations of the stated country and/or in case of parts to be exported with the approved design data and with the notified special requirements of the importing country. (over)

16 批准人签名
Signature18 批准日期
Date (d/m/y)

2 Nov 2017

17 批准人姓名(打印的)
Name (printed)

446448, Florian Langer

批准放行证书/适航批准标签

使用者/安装者职责

- (1) 必须明确: 本文件并不批准条件/组件/零件可以装到有关产品上。
- (2) 当使用者/安装者使用的足所在国适航当局高的条例, 而不是本表第1项中所指国家适航当局的条例时, 使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的条件/组件/零件。
- (3) 表中第14项、第15项的陈述, 并不说明本表是安装批准, 在所有情况下, 航空器使用前, 航空器使用者/安装者应把按本国适航条例颁发的安装批准收入维修记录中。
- AAC-038(12/94)
- LHT Form 31 (60 E-12) (HAM TQ3)

15 使用过的产品 Used Parts.

兹声明上述产品除第13项的其它规定外,已按照上述国家适航条例和进口国通知的特殊要求进行工作,该产品处于安全可用状态可以批准放行使用。

Certifies that the work specified above except as otherwise specified in block 13 was (were) carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work the part(s) is (are) in condition for safe operation and considered 'ready for release to service'. (over)

19 中国民航总局授权
Issued by or on behalf of the CAAC

F04900352

AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG

USER / INSTALLER RESPONSIBILITIES

- (1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
- (2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
- (3) Statement 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

*参阅产品目录详细查找适用性

*Cross-check eligibility for more details with parts catalogue

Workshop Report

61397844



Customer Order No.

R328487



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No.

19603805.00000001

Work Order/Contract/Invoice

61397844

Description

OUTBOARD OVERHEAD ELECTR UNIT

Part. No. as received

1167008-141

Serial No. as received

B-9104012628

Part No. as dispatched

1167008-141

Serial No. as dispatched

B-9104012628

Reason for removal

AC REG: EI-XLE
Light does not turn of

Modification Status according to Mod-Label

A

Findings

Fuse F1 defective
+5V voltage supply inoperative; capacitor C6 on service board defective
Up data failure; capacitor C9 on CCA defective
Service failure 135; capacitors C4; C14-C16 on service board defective
Capacitor C1 on service board defective

Action

Replaced fuse F1
Replaced capacitor C6
Replaced capacitor C9 on CCA
Replaced capacitors C4; C14-C16
Replaced capacitor C1
Unit passed all tests according cmm. All measurements within the required limits.

Name

446448, Florian Langer

Date (dd mmm yyyy)

02 Nov 2017

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.