

Approving Competent Authority / Country : CAA UK		AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. FORM TRACKING NUMBER. MI/23765611	
4. ORGANIZATION NAME AND ADDRESS IBERIA MAINTENANCE				Adolfo Suarez Madrid - Barajas Intl. Airport - Zona Industrial No. 2 28042 MADRID - SPAIN www.iberiamaintenance.com	
6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	RAIN REPELLENT GAGE ASSEMBLY	4020W35-3	1	5212	INSPECTED/TESTED

12. REMARKS WORKS PERFORMED I.A.W. CMM:30-45-10 REV.2 DEC 2013 Customer: AJW RO: T41179		ID PLATE DATA: DATE:01/05 AMDT:A	
---	--	----------------------------------	--

Records of works performed are on file at this maintenance organization under Work Order stated in block 5

13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part 145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.	
13b. AUTHORISED SIGNATURE	13d. APPROVAL/AUTHORISATION NUMBER	14b. AUTHORISED SIGNATURE N° DE NÓMINA 194644	14c. CERTIFICATE/APPROVAL REF. No. UK.145.01413
13c. NAME	13e. DATE(dd/mm/yyyy)	14d. NAME: PEDRO CORDERO GOMEZ	14e. DATE (dd/mm/yyyy): 03/AUG/2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from their airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national

1. Approving Competent Authority / Country AESA SPAIN		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. FORM TRACKING NUMBER. MI/23765612	
4. ORGANIZATION NAME AND ADDRESS IBERIA MAINTENANCE Adolfo Suarez Madrid - Barajas Intl. Airport - Zona Industrial No. 2 28042 MADRID - SPAIN www.iberiamaintenance.com				5. WORK ORDER / CONTRACT / INVOICE 7200696384	
6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	RAIN REPELLENT GAGE ASSEMBLY	4020W35-3	1	5212	INSPECTED/TESTED
12. REMARKS WORKS PERFORMED I.A.W. CMM:30-45-10 REV.2 DEC 2013 Customer: AJW RO: T41179 ID PLATE DATA: DATE:01/05 AMDT:A					
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No.ILAY037F. TCCA Approval Number: 898-27					
Records of works performed are on file at this maintenance organization under Work Order stated in block 5					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12					
13b. AUTHORISED SIGNATURE		13d. APPROVAL/AUTHORISATION NUMBER		14a. ☒ Part 145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.	
13c. NAME		13e. DATE(dd/mm/yyyy)		14b. AUTHORISED SIGNATURE N° DE NÓMINA 194644	
				14c. CERTIFICATE/APPROVAL REF. No. ES.145.011	
				14d. NAME: PEDRO CORDERO GOMEZ	
				14e. DATE (dd/mm/yyyy): 03/AUG/2023	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from theairworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national					

WORK SHOP REPORT

MAINTENANCE ORGANIZATION EASA PART 145 APPROVAL CERTIFICATE N° ES.145.011		FAA AIR AGENCY CERTIFICATE NUMBER ILAY037F	
IBERIA WORK ORDER	7200696384		
CUSTOMER	AJ WALTER AVIATION		
CUSTOMER REPAIR ORDER	T41179		
DENOMINATION	RAIN REPELLENT GAGE ASSEMBLY		

INCOMING DATA		OUTGOING DATA	
INCOMING DATE:	28.JUL.2023	OUTGOING DATE:	03.AUG.2023
INCOMING P/N:	4020W35-3	OUTGOING P/N:	4020W35-3
INCOMING S/N:	5212	OUTGOING S/N:	5212
MOD IN:	AMDT A	MOD OUT:	AMDT A
TASK REQUESTED:	INSPECTED/TESTED	STATUS/WORK PERFORMED:	INSPECTED/TESTED
REASON FOR REMOVAL:	IAW TO: RO		
CMM NUMBER:	30-45-10 REV.2 DEC 2013		
AIRCRAFT TAIL NUMBER:	Not reported		
ENGINE SERIAL NUMBER:	Not reported		
WARRANTY REQUESTED:	NO.	WARRANTY STATUS:	Not applicable
WARRANTY COMMENTS:	Not applicable		

EXTERNAL CONDITION / INCOMING INSPECTION:

Equipment Identification Data	☒ Yes ☐ No
Documentation	☒ Yes ☐ No
Correct config and complete	☒ Yes ☐ No
External misused (Burned, forced,	☐ Yes ☒ No

CORRECTLY PACKED AT INCOMING: YES
TYPICAL SEQUENTIAL TASKS:

Visual Incoming inspection	☒ Yes ☐ No ☐ N/A
Incoming test	☒ Yes ☐ No ☐ N/A
Disassembly	☐ Yes ☒ No ☐ N/A
Cleaning	☐ Yes ☒ No ☐ N/A
NDT Check	☐ Yes ☐ No ☒ N/A
Assembly	☐ Yes ☒ No ☐ N/A
FOD Check inspection	☒ Yes ☐ No ☐ N/A
Final Test	☒ Yes ☐ No ☐ N/A

TYPE OF FAULT:NOT FOUND FAULTY

WORK SHOP REPORT

SHOP FINDINGS AND WORKS PERFORMED:

SHOP FINDING	WORK PERFORMED
NONE.	INCOMING INSPECTION.
NO FAULT FOUND.	TEST OK.

SERVICE BULLETINS: N/A

PARTS REPLACED: N/A

SUBASSYS REPLACED: N/A

REMARKS:

ID PLATE DATA: DATE:01/05 AMDT:A