



61901965

3. Form Tracking Number

AUTHORISED RELEASE CERTIFICATE CAA FORM 1

21587254 00000001

1. Approving Competent
Authority / Country

CAA
UK

4. Organisation Name and Address



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order / Contract / Invoice

61901965

11. Status / Work

REPAIRED

8. Part No.

94830-11

9. Qty.

1

10. Serial No.

877

6. Item 7. Description
01 ISOLATOR VIBRATION

ATA 4912 TP R MK-No. 20 Pack Code 00

Resp. Workshop 33362030

Workshop Station HAM063

12. Remarks

SAFETY SEAL NO: 90316225 INSTALLED.

A.J. Walter (Aviation) Ltd. T39321

	Opr. Hours	Cycle	Opr. Day
TT	UNKNOWN	UNKNOWN	UNKNOWN
TSO	UNKNOWN	UNKNOWN	UNKNOWN
TSC	UNKNOWN	UNKNOWN	UNKNOWN
TSF	0	0	0

TASK PERFORMED IN ACCORDANCE WITH CMM 49-20-17 REV. 0

Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.

14a. ☒ Part -145.A.50 Release to Service

☒ Certifies that the items identified above were manufactured in conformity to:

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation

☐ non-approved design data specified in block 12

13b. Authorised Signature

14b. Authorised Signature

027231

13c. Approval / Authorisation Number

14d. Name

Rainer Jensen

14c. Certificate / Approval Ref. Number

UK.145.01408

14e. Date (dd mm yyyy)

01 Aug 2023

USER / INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



61901965

3. Form Tracking Number

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 21587254 00000001	
4. Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order/Contract/Invoice 61901965	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	ISOLATOR VIBRATION		1	877	REPAIRED
12. Remarks A.J. Walter (Aviation) Ltd. T39321 TP R MK-No. 20 Pack Code 00 Resp. Workshop 33362030 Workshop Station HAM063 SAFETY SEAL NO: 90316225 INSTALLED. Opr. Hours Cycle Opr. Day UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0 TASK PERFORMED IN ACCORDANCE WITH CMM 49-20-17 REV. 0					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☒ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.					
14b. ☒ Other Regulation specified in block 12					
Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents					
Return to Service in Accordance with 14 CFR part 43 The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under FAA Certificate No.: DLAY225D TCCA Approval No.: 897-08					
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref. Number	
		027231		DE.145.0001	
13d. Name		13e. Date (dd mm yy)		14e. Date (dd mm yy)	
				01 Aug 2023	

EASA FORM 1 - Issue 3

USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

Lufthansa Technik



Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

G1901965

Certificate Ref. No.

21587254 00000001

Work Order/Contract/Invoice

61901965

Description

ISOLATOR VIBRATION

Responsible Workshop

33362030

Modification Status according to Mod-Label

See Unit Mod-Label if equipped

Customer Order No.

T39321

Part No. as received

94830-11

Part No. as dispatched

94830-11

Serial No. as received

877

Serial No. as dispatched

877

Reason for removal

PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS

TEST:

REMOVED IN SERVICEABLE CONDITION FROM A/C REGN: EC-NIE

THIS UNIT WILL BE COMING BACK INTO AJW STOCK AFTER REPAIR AND RELEASE.

I CAN CONFIRM THIS WILL NOT BE RELEASED TO ANY CURRENT SANCTIONED

COUNTRY.

IN ACCORDANCE WITH OUR STANDARD TERMS AND CONDITIONS AVAILABLE ON THE

JWWEBSITE.

SEE SECTION 14 IN OUR STANDARD TERMS AND CONDITIONS

Findings

ISOLATOR ARRIVED IN CONTAMINATED CONDITION. DISASSEMBLY AND CLEANING FOR INSPECTION NECESSARY.

MINOR SURFACE DEFECTS ON HOUSING; POLISHING AND PASSIVATING NECESSARY.

MOLDED CORE DIMENSIONS OUT OF LIMIT; REPLACEMENT NECESSARY MEASURED 40,40mm.CMM LIMIT IS 40,89mm

BOLTS CORRODED AND WASHERS WORN.

Action

ISOLATOR DISASSEMBLED AND ALL COMPONENTS CLEANED AND INSPECTED.

HOUSING DIMENSIONAL INSPECTED ACC. TO CMM WITHOUT COMPLAINT.

MINOR SURFACE DEFECTS ON HOUSING REMOVED BY LOCAL POLISHING.

MPI CHECK PERFORMED WITHOUT COMPLAINT.

HOUSING PASSIVATED.

NEW MOLDED CORE INSTALLED.

BOLTS AND KEY WASHER REPLACED.

ISOLATOR COMPLETED AND SEALED.

Name

27231, Rainer Jensen

Date (dd mm yyyy)

01 Aug 2023

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

RFID-Smartlabel

61901965



Ident-Tag Barcode

Ident-Tag



Lufthansa Technik

Form Tracking Number
21587254 00000001

Work Order / Contract / Invoice

Description
ISOLATOR VIBRATION

Part. No.
94830-11

Eligibility

Quantity
1

Status / Work
REPAIRED

Serial-/Batch No.
877

Remarks
TP R MK-No. 20
FSCM 13636 ATA

Resp. Workshop 33362030 Workshop Station HAM063

SAFETY SEAL NO: 90316225 INSTALLED.

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

Removed

PNR¹

SNR¹

Position/FIN No.¹

Station¹

A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹

☐ 22 Unscheduled

Complaint No.¹ or WO-Reference¹

☐ 11 Scheduled

Failure Description¹ (Please write in capital letters only)

CCI-ID²

Stamp or ID Number + Signature^{1/2}

Date¹

¹ Mandatory entries without using CCI-Mask
² Mandatory entries using CCI-Mask

LHT Form 31794 E-20 (FRA T/FS-QP)

Special Investigation Tag exists ☐ Yes

Please send back to:(unless other return location is agreed)

LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLBUETTEL
Deutschland

(LTLS-Information: Use this box for ZID)