

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 63629	
4. Organisation Name and Address OAKENHURST AIRCRAFT SERVICES LTD Claydons Lane, Rayleigh, Essex SS6 7UP Tel: 44(0)1268 741622 Fax: 44(0)1268 741650 http://www.oakenhurst.com avionics@oakenhurst.com		Trading as OAKENHURST THE AVIONICS WORKSHOP		5. Work Order/Contract/Invoice 197360			
6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status/Work		
1	Liquid Quantity Transmitter LAST ITEM	391046-05131	1	4455B	Repaired		
12. Remarks		A J WALTER (AVIATION) LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD WEST SUSSEX RH13 0SH					
IN ACCORDANCE WITH MANUFACTURERS MANUAL No 28-41-05 REVISION R11, 30th June 1999							
DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5							
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No O5KY452Y							
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ PART-145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with PART-145 and in respect to that work the items are considered ready for release to service		14b. Authorised Signature 		14c. Certificate / Approval Ref No. UK.145.00524	
13b. Authorised Signature 		13c. Approval / Authorisation Number UK-21G.2368		14d. Name Alan Hudson		14e. Date (dd/mm/yyyy) 06/Feb/2013	
13d. Name							

NOTE:

1. This certificate does not automatically constitute authority to install the item(s).
2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

USER / INSTALLER RESPONSIBILITIES

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2.				AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number 63629			
4. Organisation Name and Address OAKENHURST AIRCRAFT SERVICES LTD Claydons Lane, Rayleigh, Essex SS6 7UP Tel: 44(0)1268 741622 Fax: 44(0)1268 741650 http://www.oakenhurst.com avionics@oakenhurst.com						Trading as 						5. Work Order/Contract/Invoice 197360	
6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status/Work								
1	Liquid Quantity Transmitter LAST ITEM	391046-05131	1	4455B	Repaired								
12. Remarks						A J WALTER (AVIATION) LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD WEST SUSSEX RH13 0SH							
IN ACCORDANCE WITH MANUFACTURERS MANUAL No 28-41-05 REVISION R11, 30th June 1999													
DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5													
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12						14a. ☒ PART-145 A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with PART-145 and in respect to that work the items are considered ready for release to service							
13b. Authorised Signature						14b. Authorised Signature  14d. Name Alan Hudson							
13c. Approval / Authorisation Number UK 21G.2368						14c. Certificate / Approval Ref No. UK.145.00524							
13e. Date (dd/mm/yyyy)						14e. Date (dd/mm/yyyy) 06/Feb/2013							
13d. Name													

NOTE:

USER / INSTALLER RESPONSIBILITIES

1. This certificate does not automatically constitute authority to install the item(s).
2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

The Avionics Workshop Shop Movement Order

El

Job No: <u>AVW WKSP 63629</u> Description: <u>Liquid Quantity Transmitter</u> Part No: <u>391046-05131</u> Serial No: <u>4455B</u> Customer: <u>A J WALTER (AVIATION) LTD</u> Order No: <u>197360</u> Order Responsible Person: <u>LAURA SALADO</u> Customs No: _____ Customs Date: _____ Tail No / Type: <u>UR-VVA</u> End Use No: <u>EU/0903/102/13 expiry 31st</u> Currency: <u>STERLING</u>	Date Received: <u>28 January 2013</u> Date Required: _____ Manufacturer: <u>BF Goodrich</u> Mechanic: <u>Azher Mohammed</u> Manual Ref: <u>28-41-05</u> Manual Date: <u>R11, 30th June 1999</u> Date Completed: <u>06 February 2013</u> Despatch Note No: <u>76398</u>
--	---

Work Required: CAA: ☒ FAA: ☒ C of C: ☐ TCCA: ☒ Reported Defect: ☐ Warranty: ☐ REPAIR UNDER T&M PLEASE QUOTE AND HOLD	UNIT WAS FOUND INOP
---	---------------------

Despatch: A J WALTER AVIATION	Customer Coding <u>B</u>
---	---------------------------------

Overhauled: ☐ Repaired: ☒ Inspected - Tested: ☐ Modified: ☐

Remarks: (EASA Form 1)

THE DESCRIBED MAINTENANCE HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE AIRWORTHINESS REQUIREMENTS UNDER OUR APPROVAL NUMBER T.C.C.A :807-10

Strip Report:

Warranty: **Accepted:** ☐ **Denied:** ☐

UNIT RECEIVED IN AVERAGE CONDITION. REPORTED DEFECT NOT CONFIRMED. CAPACITANCE READING TOO HIGH DUE TO HEAVY CONTAMINATION. UNIT THOROUGHLY CLEANED, FULLY TESTED I.A.W. MANUFACTURERS DATA AND OPERATES SATISFACTORILY.



Mech Sig *mdr* **Insp** _____ **Date** 06/02/2013

Q.C. Comments \ Investigation (if warranty claim)

Sig _____ **Insp** _____ **Date** _____

History Report

Part No 391046-05131

Serial No 4455B

Job No AVW WKSP 63629

Warranty No

Accepted No

Date Released 06 February 2013

Customer A J WALTER (AVIATION) LTD

Work Required

Tail No UR-VVA

Despatch Note No 76398

REPAIR UNDER T&M PLEASE QUOTE AND HOLD

Reported Defect

UNIT WAS FOUND INOP

Strip Report

UNIT RECEIVED IN AVERAGE CONDITION. REPORTED DEFECT NOT CONFIRMED. CAPACITANCE READING TOO HIGH DUE TO HEAVY CONTAMINATION. UNIT THOROUGHLY CLEANED, FULLY TESTED I.A.W. MANUFACTURERS DATA AND OPERATES SATISFACTORILY.
