


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 25688	
4. Organization Name and Address: MTI Aviation, Inc. 13150 NW 45th AVENUE OPA LOCKA, FL 33054 Ph: 305-817-4244, Fax: 305-817-4241 info@mtiaviation.com FAA CRS #: Q8VR235Y				5. Work Order/Contract/Invoice Number: WO1019330	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	CONTROL VALVE	3291238-2	1.00	3030	TESTED
12. Remarks: Unit TESTED I/AW CMM ATA:49-52-31 REV: 10 DATED: 11/APR/2022 No FAA or EASA S/B and AD's complied with at this shop visit. Full details of work carried out held on Work Order WO1019330					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval No. 145.6145					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
				14c. Approval/Certificate No.: Q8VR235Y	
				14d. Name (Typed or Printed): ROBERTO PEREZ	
				14e. Date (dd/mm/yyyy): 14-Feb-2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



MTI AVIATION, INC.

13150 NW 45TH AVENUE
OPA LOCKA, FL 33054
PH: 305.817.4244

FAA CRS #: Q8VR235Y
EASA #: 145.6145

Work Order

Work Order #: WO1019330
Customer #: 047440
Part Number: 3291238-2
Serial #: 3030
Date Printed: 2/14/2023
Page: 1

To: SETNA IO
2900 W. CHICAGO AVENUE
CHICAGO, IL 60622
UNITED STATES

WO Status
OPEN

Work Type: TEST
Department: PNE - PNEUMATICS
Location : A2
Warranty: No
Incoming Part #: 3291238-2
Outgoing Part #: 3291238-2
Description: CONTROL VALVE

Terms:
Serial #: 3030

Phone #: 312-549-4459
Fax #:
Email: david@setnaio.com

Entry Date: 1/11/2023

PRELIMINARY INSPECTION:

VERIFIED PN AND SN PER ID PLATE.

DATE: 2/14/2023 INSPECTOR: ROBERTO PEREZ

PRE TEST:

UNIT PASSED ALL FUNCTIONAL TEST.

DATE: 2/14/2023 INSPECTOR: ROBERTO PEREZ

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

UNIT WAS TESTED, CLEANED, & INSPECTED PER MFG'S SPECS.

TEST RESULTS ARE AS FOLLOWS:
-UNIT PASSED ALL FUNCTIONAL TESTS
-NO FAULTS FOUND

NOTE: NICKS, DENTS, SCRATCHES DO NOT AFFECT FIT FORM OR FUNCTION OF UNIT.

TECHNICIAN: IVAN GRANADOS DATE: 2/14/2023 INSPECTOR: ROBERTO PEREZ

FINAL INSPECTION:

N/A

DATE: 2/14/2023 INSPECTOR: ROBERTO PEREZ

CORRECTIVE ACTION:

ALL DISCREPANCIES NOTED IN TEAR DOWN WERE CORRECTED.
UNIT WAS REASSEMBLED, TESTED, AND FINALIZED IAW
CMM ATA:49-52-31 REV: 10 DATED: 11/APR/2022
UNIT RETURNED TO SERVICE TESTED

TECHNICIAN: IVAN GRANADOS DATE: 2/14/2023 INSPECTOR: ROBERTO PEREZ

MODIFICATION / SERVICE BULLETINS:

N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS TESTED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE WORK ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by

Date 2/14/2023

MTI Aviation, Inc.
13150 NW 45th AVENUE
OPA LOCKA, FL 33054
Ph: 305-817-4244, Fax: 305-817-4241
info@mtiaviation.com

WO Packing Slip

WO #: WO1019330

Date: 2/15/2023

Time: 12:42:27 PM

Page: 1

To:

SETNA IO
2900 W. CHICAGO AVENUE
CHICAGO, IL 60622
UNITED STATES

Ship To:

SETNA IO GLOBAL HEADQUARTERS
475 BOND ST.
LINCOLNSHIRE, IL 60069
UNITED STATES

Order Date: 1/11/2023

Prepared By: RECV-SHIP

Customer #: SI3

Buyer: DAVID CHAIMOVITZ

Ship Via: _

Ship Via Acc:

Part Number/Description

Qty

3291238-2 CONTROL VALVE

1

Loc/Whse:

Serial #: 3030

WO1019330 SHIPPED VIA FEDEX TRK 7713 1376 0049 ON 2/15/23