Approving Civil Aviation     Authority/Country:		2.				3. Form Tracking Number.	
FAA/UNITED STATES		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				712958	
Accesso	nization Name and Address ry Technologies Corpo air Station Certificate	oration	, 41 Mercedes Way U			5. Work Order, Contract, or Invoice Number:	
6. Item:	7. Description:	8.	Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	ACTUATOR, APS INLET DOOR		732-13870-12	1	128-1002	REPAIRED	
12. REMAI Item depi Manufact Modificati	cted in blocks 6 through urer Name SHIMADZU	10 has Overha	been serviced as indical beaul Manual Report Nur	cated in block nber <u>49-15-06</u>	11, in accordance with t , Revision <u>12</u> , Dated <u>05</u> ,	he following FAA approved data: 14/2020, Service Bulletin(s) and/or	
accorda		145 ar	nd with respect to t	hat work, th	e aircraft componen	nd 12 was performed in t is considered ready for release	
	s the items identified above w					e  Other regulation specified in Block 12	
	ed design data and are in a proved design data specific			11 and de Code of Fe	scribed in Block 12 was a	ed in Block 12, the work identified in Block accomplished in accordance with Title 14 and in respect to that work, the items are	
13b. Authorized Signature:		13c. No:	Approval Authorization	14b. Authorized Signature:		14c. Approval/Certificate No: Y4AR039O	
3d. Name (Typed or Printed):		13e.	Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):  Raheel Khan		14e. Date (dd/mmm/yyyy):  07/MAR2022	
					Traine or Trinair		
			User/Insta	aller Respoi			
Where the the country he airworth	user/installer performs wor specified in Block 1 it is e niness authority of the cour in Blocks 13a and 14a	rk in acc ssential stry spec	e of this Document alone or ordance with the national that the user/installer ensified in Block 1.	does not autom regulations of sures that his/her	atically constitute authority of an airworthiness authority are airworthiness authority are	to install the part/component/assembly.  ifferent than the airworthiness authority of kacepts parts/components/assemblies from an installation	

Ç

## # ACCESSORY TECHNOLOGIES AWENCOR GROUP COMPANY TECHNOLOGIES Corporation

A WENCOR GROUP COMPANY
http://www.atcny.com 41 Mercedes Way Unit #34 Edgewood, NY 11717
FAA CRS: Y4AR0390 EASA: 145.4014 631-753-2282 (Phone) 631-753-2407 (Fax)

**Customer Service Report** 

Work Order #:

712958

Page: 1

CUSTOMER: A J WALTER (AVIATION) LTD

REF #: R389039

TAIL #: G-OOBB ATA: 49-15-06

OEM: SHIMADZU

DESCR: ACTUATOR

P/N RECEIVED: 732-13870-12

P/N SHIPPED:

S/N: 128-1002

OPEN DATE: 12/3/2021

WARRANTY No

CONTAINER: N/A

WORK REQUESTED: Repair

WORK PERFORMED: Repair

REASON FOR REMOVAL: Customer request/ INOP and Replace data plate.

CONFIRMED: Yes.

INCOMING INSPECTION: O.K. Externally

TEARDOWN INSPECTION: Motor contaminated. Armature open Slingers bent. Bearing worn. Plates worn.

WORK PERFORMED: Partially disassembled Unit. Performed required inspections. Replaced all material as required. Reassembled and tested. All work performed I/A/W the latest Shimadzu CMM. O.K. to return to service.

PN	Description	Qty Issued	CD
732-16992	PLATE	1.00	NE
732-17110	WASHER	1.00	NE
734-15698-03	NAMEPLATE	1.00	NE
M25988-3-022	PACKING	1.00	NE
M25988/3-128	PACKING	1.00	NE.
R3073001-1	BEARING	1.00	NE
R3073002-1	BEARING	1.00	NE
R3073004-1	SLINGER	1.00	NE
R3073005-1	SLINGER	1.00	NE
R3103100-3	ARMATURE	1.00	ОН

AU	П	OR	IZED	SIG	NAT	URE:
				1		
				1.1	7	
			/	11/	/	/

DATE:

Mar/07/2022

Form ATC-002

Rev 2 12/14/20