

1. Approving Competent Authority/Country
CAA / United Kingdom

2.

AUTHORISED RELEASE CERTIFICATE
CAA FORM 13. Form Tracking Number
ARC86188

4. Organisation Name and Address

Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622
Email: sales@oakenhurst.com
Web: www.oakenhurst.com5. Work Order/Contract/Invoice
WP78370 / T38720

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Battery Pack	D717-01-100	1	428536	Repaired

12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under FAA certificate no. 05KY452Y.

Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 24-35-01, Rev 12, 01/05/2020.

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation
☐ Non-approved design data specified in block 12

14a. ☒ Part-145.A.50 Release to Service☒ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
		<i>Rolie</i>	AVW 46 UK.145.00524
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Ricky Dulieu	08 Aug 2022

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority/Country	2.	3. Form Tracking Number
EASA		ARC86189

4. Organisation Name and Address	5. Work Order/Contract/Invoice
OAKENHURST AIRCRAFT SERVICES LTD	WP78370 / T38720

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Battery Pack	D717-01-100	1	428536	Repaired

12. Remarks
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 24-35-01, Rev 12, 01/05/2020.

13a. Certifies that the items identified above were manufactured in conformity to:	14a. <input checked="" type="checkbox"/> Part-145.A.50 Release to Service	<input type="checkbox"/> Other regulation specified in block 12
<input type="checkbox"/> Approved design data and are in condition for safe operation	Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
<input type="checkbox"/> Non-approved design data specified in block 12		

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
		AVW 46	EASA.UK.145.00524
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Ricky Duileu	08 Aug 2022

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

CAA Part 145: UK.145.00524

EASA Part 145: EASA.UK.145.00524

Completion Report

No: **WP78370**

Issue: **03**

Date: **08-Aug-22**

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom

Attn: Ahlem Morris

Tel: 0044 (0) 1403 798000 Fax:

E-Mail: Ahlem.Morris@ajw-group.com

Your Ref: T38720	Our Ref No: WP78370	Test Required: N/A	
Part No: D717-01-100	Description: Battery Pack	TSN: N/A	CSN: N/A
Serial No: 428536	Workscope: FP&E-M Repair	TSO: N/A	CSO: N/A
DoM:	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No: A6-LRC	Position:

Technical Reference: LIB01618 - Issue No: N/A - Rev No: 12

Inspection Findings:

Unit received for test and recertify. Unit passed all testing. Unit disassembled for inspection. Inspection found battery has broken lug. Upon approval unit requires repair of battery, re-assembly, charge of battery and final checks.
Damage is C.I.D.

Completion Summary:

Battery broken Lug repaired and final testing completed.

Signed:

Name:

Date:

08/08/22

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP