1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number.
FAA/UNITED STATES	**AUTHORIZED RELEASE CERTIFICATE** FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	**22902**

4. Organization Name and Address.	5. Work Order, Contract or Invoice Number:
Ametek MRO Florida Inc. **dba Avtech Avionics & Instruments** **7370 NW 35th Street** **Miami, FL. 33122** **US** Repair Station No.: **1VTR273B**	Work Order No.: **ARA100341** Customer RO.: **R268586**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	CONTROL PANEL	622-5129-105	1.00	2055	REPAIRED

12. REMARKS

CMM: 34-45-14 Rev: 3 Date: 02-Jun-2015

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number EASA.145.6180.

13a. Certifies the items identified above were manufactured in conformity to:		14a [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12	
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature:	14c. Approval/Certificate No: 1VTR273B
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): Greta Herrera	14e. Date (dd/mmm/yyyy): 28/Jul/2015

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Ametek MRO Florida Inc.
dba Avtech Avionics & Instruments
7370 NW 35th Street
Miami, FL. 33122
US

Tear Down/Inspection

Work Order #: ARA100341
Date Completed: 28/Jul/2015
PO Number: R268586

To:
AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS
UNITED KINGDOM

Ship To:
AJ WALTER AVIATION LTD
B&H
8000 NW 25TH STREET SUITE 300
DORAL,FL 33122 US

Part Number:	622-5129-105	**Serial Number:**	2055
Description:	CONTROL PANEL	**Manufacturer:**	COLLINS AVIONICS
Service Performed:	REPAIRED	**Repair Station:**	1VTR273B

Data Used: Manual Number: 523-0818661 Rev: 3 Date: 02-Jun-2015

Teardown/Inspection Data

1.Reason for Removal: Radar pitch shows one degree lower than assigned.
Inst: Repair as necessary

2. Initial Inspection Findings
Appearance: Normal
Corrosion: No Corrosion Noted.
Loose or Missing Parts: No Loose or Missing Parts.
Physical Damage: No damage found.

3. Teardown
Dissassembly: Only as Required for Repair
Cleaning: Performed cleaning as required
Painting: None Performed.
Assembly: As Required

4. Test
Was Complaint Verified: Yes
Operation: TESTED I/A/W Mfg Specs.
Modifications: NONE
Other problems found: Repaired

5. Final
Warranty Accepted: N/A
Final Test and Inspection: Final Inspection Normal
A.D. S.B. NO A.D. / S.B. REQUIRED

6, Work Performed: Reworked chassis assy and bench check according to MFR's Spec's.

MAINTENANCE RELEASE

This certifies the item identified above was serviced in accordance with current F.A.A. airworthines regulations and in respect to the work performed is approved to return to service. Pertinent details of the work peformed are on File at this Agency under Work Order No:- ARA100341

Inspector's Name : Greta Herrera
Technician: Jose Davila

Signature: _____ Date: 28/Jul/2015