

1. Approving Civil Aviation
Authority/Country:

2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

243326

4. Organization Name and Address:

Aero Accessories & Repair, Inc.

FAA CERT #77AR783B

15501 SW 29TH ST. SUITE#201

MIRAMAR, FL 33027

Ph: 954-266-1300,

5. Work Order/Contract/Invoice
Number:

58132

R412431

FAA Approval Holder: 77AR783B

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 WING ILLUMINATION LIGHT ASSEMBLY

81000-37703

1

8848

TESTED

12. Remarks:

The component identified above was TESTED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.

S/B and A/D: None Applicable.

OEM CMM: 33-41-02, Revision#: 6, Revision Date: 2/19/2016

ORIGINAL

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

WELCEMEN B. JEANNOT

77AR783B

21-Jun-2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Work Order**Work Order #: 58132**

Date Printed: 6/21/2023

Time: 4:17:19 PM

Page: 1

To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:

B&H WORLDWIDE
1523 NW 82 AVENUE
DORAL, FL 33126
UNITED STATES

Ref #: R412431

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 81000-37703

Descr: WING ILLUMINATION LIGHT ASSEI

Qty: 1

Station: AVIONICS

Make:

Model:

Mfg: Koito

Repair Manual(s): 33-41-02 Rev: 6 Rev. Date: 2/19/2016

Entry Date: 6/14/2023

Need Date: 6/22/2023

Compl. Date: 6/21/2023 4:16

Warranty: No

Container:

Serial Numbers: 8848

RECEIVING INSPECTION

P/N and S/N verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

PRELIMINARY INSPECTION

P/N 81000-37703 S/N 8848 verified through ID plate and customer RO.

TSN: unk CSN: unk

TSO: unk CSO: unk

Tech: A Tur, # 72

HIDDEN DAMAGE

None noted.

Tech: A Tur, # 72

INITIAL FINDINGS

Unit passed IAW technical data referenced above.

Customer Complaint: No verified

Tech: A Tur, # 72

TEARDOWN FINDINGS

Unit cleaned and inspected IAW technical data referenced above. Minor nicks, scratches, and dents do not affect fit, form, or function of the unit.

Unit passed functional test

Bench Test Quote

Tech: A Tur, # 72

CORRECTIVE ACTION

Unit was inspected & tested IAW technical data referenced above.

Tech: A Tur, # 72

Authorized Signature: _____

Name: WELCEMEN JEANNOT

Date: 6/21/2023