

Serviceable Tag



Head Office
WOW Air
Katrínartún 12
105 Reykjavík
Iceland

1. Serviceable Tag Number

Tag #: 6032



Runn. #: 11893

2. Part Name

IN - SEAT POWER SUPPLY

3. Part Number

3E2Y8 / 1191-38

4. Serial number

112232

5. Aircraft mfr.

6. Component Status / Remarks

TSN: 2941.100

CSN: 696

Cert. #: RMA88070

ATA:

R #: 11893

H. Note: COMOPONENT STATUS AS PER INCOMING CERTIFICATION AS STATED IN BLOCK 6

9. Vendor / Supplier

ASTRONICS AES

10. Site / Rack / Shelf

KEF/N1-1/ROT B3-4/*

11. Purchase order

14010

12. Shelf life expiration

01-Jan-9999

Life limited parts will be accompanied by maintenance history including life

Receiving Inspection

Receiving inspection accomplished in accordance with CAME procedure, chapter 2-2.

13. Signature / Stamp

AIO WOW AIO IS.145.01

14. Approval reference number

IS.145.019

15. 3 letter code

AIO

16. Date (dd-mmm-yyyy)

05-Mar-2018

Installation Data

Forward to Maintenance Planning

17. Installed on A/C ref

18. Position

19. Site Code

20. Tech log page #

21. Date

22. Signature / Stamp

Removal Data

Duplicate removal data below

23. Part number

25. Component status ☐ Removed servicable ☐ Removed unservicable

24. Serial number

26. Reason for removal ☐ Timex ☐ Snag ☐ Tr.shoot ☐ Mod ☐ Incident

17. Removed from A/C ref

18. Position

27. Failure / further description

M-41 Rev. Original

Tear off

This line needs to be perforated

Component Identification Tag

Attach to removed component

Incoming Serviceable Tag #: 6032

Runn. #: 11893



17. Removed from A/C ref

18. Position

19. Site Code

20. Tech log page

21. Date

22. Signature / Stamp

23. Part Number

24. Part Name

25. Serial number

26. Component status ☐ Removed servicable ☐ Removed unservicable

28. Work order #

29. Work card

27. Reason for removal ☐ Timex ☐ Snag ☐ Tr.shoot ☐ Mod ☐ Incident

30. Failure / further description