

1. Approving Civil Aviation
Authority/ Country:
FAA/United States

2.

Authorized Release Certificate

FAA Form 8130-3, Airworthiness Approval Tag

3. Form Tracking Number:

138577

4. Organization Name and Address:

Aviation Instruments Repair Specialists, Inc.
A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A.
Phone: (305) 887-5600 Fax: (305) 820-0931

5. Work Order/Contract/
Invoice Number:

R312199

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	FUEL QTY IND.	10037-1000-0153	1ea.	301	REPAIRED

12. Remarks:

REPAIRED in accordance with CMM: 28-42-02 Revision: 7 Date: 8/1/1999

Full details of work carried out per work order no. 138577

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the FUEL QTY IND. is considered ready for release to service under EASA Part 145 approval no. EASA EASA.145.5033.

No applicable A.D. or S.B. Required.

ECCN #9A991D.

13a. Certifies the items identified above were manufactured in conformity to:


☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature: Not Applicable	13c. Approval/Authorization No.: Not Applicable	14b. Authorized Signature: 	14c. Approval/Certificate No.: VTBR433V
13d. Name (Typed or Printed): Not Applicable	13e. Date (dd/mm/yyyy): Not Applicable	14d. Name (Typed or Printed): Marshall Garber	14e. Date (dd/mm/yyyy): 12/Apr/2017

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: (305) 887-5600 Fax: (305) 820-0931

C.R.S. No.: VTBR433V

Work Order: 138577

Date: April/12/2017

Phone:(305) 887-5600

Fax: (305) 820-0931

Sold To:

A J WALTER AVIATION
The Headquarters, Maydwell Ave. Slinfold
West Sussex RH13 0SH, UK

Ship To:

B&H Worldwide Inc.
8000 NW 25th Street Suite 300
Doral, Florida 33122

Part Number: 10037-1000-0153

Serial: 301

Manufacturer: BF GOODRICH

Description: FUEL QTY IND.

Model: 10037-1000-0153

Purchase Order: R312199

Service Performed: REPAIRED

Data used: Manual Number: 28-42-02 Revision: 7 Date: 8/1/1999

TearDown/Inspection Data

1. Removal: SEE REPAIR ORDER.

Inst.: REPAIR

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Corrosion: No Corrosion Noted

Loose or Missing Parts: No Loose or Missing Parts

Physical Damage: No Damage Found

Mod. Level: N/A

3. Teardown

Dissassembly: Normal

Cleaning: Normal Cleaning

Painting: Normal Painting

Assembly: Normal Assembly

4. Test

Operation: LCD Damaged

Was Complaint Verified: N/A

Mods. Completed: None

5. Final

Warranty Accepted: N/A

Final Test and Inspection:

Final Inspection Normal

T.S.O.: TSO

A.T.A.: 28-42-02

A.D. S.B. NO A.D. / S. B. REQUIRED

Work Done: UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, ASSEMBLED. REPLACED DISPLAY ASSEMBLY AND REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 28-42-02. WORK BY EYDA DOMINGUEZ, ECCN #9A991D.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 138577

Inspector's Name: Marshall Garber

Technician: Eyda Dominguez

Certificate No. 2506369

Signature: _____

Date: April/12/2017

Form CRS-3