

1. Approving Civil Aviation Authority Country Transport Canada 		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking No. 20196146	
4. Organization - Name and Address MTU Maintenance Canada Ltd. 6020 Russ Baker Way Richmond, BC, Canada V7B 1B4		5. Work Order/Contract/Invoice P.0631727.01		5. Work Order/Contract/Invoice P.0631727.01	
6. Item 1		7. Description CHIP COLLECTOR MAGNETIC PLUG		8. Part No. 1A6794-1	
9. Qty. 1		10. Serial/Batch No. N/A		11. Status/work INSPECTED/TESTED	
12. Remarks UNIT INSPECTED AND TESTED IN ACCORDANCE WITH OEM CMM 79-22-10 REVISION 0, DATED 15 DEC 1997. SB(s): NONE TSN: UNK TSO: UNK CSN: UNK CSO: UNK REMOVED FROM ESN: V10920 CHIP COLLECTOR PLUG P/N: 1A6794-1 S/N: 0124 For additional details please refer to the attached component teardown/inspection report and parts list. Signature <i>[Signature]</i> Date 28 Nov 2019 For MTU Maintenance Canada Ltd. Approval No. 112-98 EASA-145 Approval Certificate Reference Number EASA.145.7077 Customer: AJW Aviation					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non approved design data specified in block 12.					
14a. ☒ CAR 571.10 Maintenance Release ☒ Other regulations specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, has been performed in compliance with the Canadian Aviation Regulations.					
13b. Signature N/A		13c. Approved Organization Number N/A		14c. Approved Organization Number AMO 112-98	
13d. Name N/A		14d. Name Holguer (Daniel) ZAMBRANO		14e. Date (dd/mm/yyyy) 28 Nov 2019	

(Previously form 24-0078)

Installer Responsibilities

This certificate does not constitute authority to install.

Installers working in accordance with the national regulations of a country other than that specified in block 1 must ensure that their regulations recognize certifications from the country specified.

Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.



COMPONENT TEARDOWN/INSPECTION REPORT

Customer:	AJW Aviation	WBS/P No:	P.0631727.01
Customer PO/RO No:	T33278	Engine Type:	V2500
Completion Date:	2019-11-21	Ex Engine S/N:	V10920

Description:	CHIP COLLECTOR magnetic plug	Quantity:	1
---------------------	------------------------------	------------------	---

Part Number IN:	1A6794-1	Serial Number IN:	NA
Part Number Out:	Same as Incoming P/N	Serial Number Out:	Same as Incoming S/N
TSN:	UNK	TSO:	UNK
CSN:	UNK	CSO:	UNK

INCOMING / SHOP FINDINGS:

No visible external damage noted.

Work Accomplished: Inspected/Tested

Manual Reference:

CMM 79-22-10 REV.0 Dated 15 DEC 1997.

Service Bulletin(s) Accomplished:

None

Technical Orders (DER) Accomplished:

None

Additional Information:

Chip Collector Plug P/N :1A6794-1 S/N:0124

Parts List Attached: Yes

Test Report Attached: Not Applicable

Created by: Ricky Yau

YKC: YKC3084

Availability list for materials for operations

Exc.	Order short text	Order	Bas. Start	Item	Material	Material description	Reqmnt qty	Quantity	Qty.withdr
O (	P.0631727.01 AJW MC APPROVED RICKY	20103784108	11/19/2019	0010	44066	Packing	1	1	1
O *	P.0631727.01 AJW MC APPROVED RICKY	20103784108	11/19/2019	0010	1A6794-1	CHIP COLLECTOR magnetic plug	1	0	0
*	*	20103784108					2	1	1