AOG Reaction

526 Aviator Drive Fort Worth, TX 76179-5425

SERVICEABLE PART

F.A.A. REPAIR STATION TU1R519K

(817) 439-0700 FAX (817) 439-9700

									W (011) 403-3	
l. Appro Autl	ving National	Aviation y:	2.					3. Form Tracking	ng Number:	
FA	A/INITED	AUTHORIZED RELEASE CERTIFICAT								
7 1 12	TOTALLEL	STATES	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG						102251	
4. Organi	ization Name	and Address:						5 Work Orde	er/ Contract/Invoice	
AOG	Reaction,	Inc. 526 Aviator D	Drive, Fort Worth, TX	ort Worth, TX 76179				Number:		
6. Item:								W.O.# 102251		
o. Item:	1	Description:	8. Part Number:		9. Eligibility:*	10. Quantity:	11. Seria	al/Batch Number:	12. Status/Work:	
1	Temp Ser Rosemon		154DB3		N/A	1	G3777		INSPECTED	
13. Remai	rks: Des	cription of Work P	erformed.							
*AOG Re	MEETS OF See Teaction certifications	EM SPECIFICATI ardown/Analysis Rules that the work specific	PER 73-21-33 REV NO ONS eport for further details ied in Blocks 12 and 13 was tred ready for release to servi	nerformed	in accordance	rith EASA Imple	ementation	Rule part 145 appr	roval, and with respect	
			nanufactured in conformity t	-	et	R 43.9 Return to		X Other regula		
			ondition for safe operation.		A I I	ic 43.5 Rotuin to) Selvice	Mother regula	tion specified in Block	
	Non-approve	d design data specified	in Biock 13.		identified in accorda	m block 12 and ince with Title 1	described 4, Code of	ied in Block 13, the in Block 13 was a Federal Regulation are approved for re	ccomplished ns. part 43	
	15. Authorized Signature: N/A		16. Approval/Authorization No: N/A		20. Authorized Signature:			21.	Approval/Certificate No: TU1R519K	
7. Name (Typed or Printed):			18. Date (m/d/y):		22. Name (Typed-or Printed):			23. 1	Date (m/d/y):	
A Form 8130-3 (6-0	01)	N/A	N/	'A	Ro	bert Samson			Feb/20/200	
Customer:		AV Blue LLC	TEARDOV		th applicable technical data ALYSIS RE	PORT			NSN: 0052-00-01	
Customer Agent:		Andy Murphy			Customer's RO: 215-07					
art Numl		Date received: Feb/19/2007 Serial number: G3777								
	enclature:	Temp Sensor		АТА	A Code: 73			And an address of the design o		
lanufactu		Rosemount								
emoved I	From:	AV BLUE STOCK						6 0	A	
ime on Pa	art:	NTC						S.P	: 3	
efect Rep	ported:	AIR WORTHINESS INSPECTION								
efect Con	nfirmed?:		AD Notes, Service Bull	letins Ap	plicable: No	ne		ita	20	
10p Inspe	ection/Test	Findings: TESTED	OK. NO DEFECTS NOTE				.07	air CERTI	Signatul	
ork Acco	omplished:	CLEAN INSPECT & MEETS OEM SPECI	TEST PER 73-21-33 REV I	Nov/01/20	02	08.05	34.67			
						-01	W			

AOG Reaction, Inc FAA Repair Station - TU1R519K 526 Aviator Drive Fort Worth, TX 76179-542 (817) 439-0700

Teardown/Analysis Report

Work Order 102251

Customer

AV Blue LLC

Customer's RO Number: 215-07

Customer's Agent

Andy Murphy

Date Received: 02/19/07

Part Number 154DB3

Serial number G3777

ATA Code: 73

Nomenclature Temp Sensor

Rosemount

Manufacturer

Removed From AV BLUE STOCK

Time On Unit NTC

Defect Reported AIRWORTHINESS INSPECTION

Defect Confirmed?

N/A

Shop Inspection Findings: TESTED OK. NO DEFECTS NOTED

Work Accomplished: CLEAN INSPECT & TEST PER 73-21-33 REV 11/01/02 MEETS OEM SPECIFICATIONS

Work Performed By:

Jakob Harrell

02/20/07

Robert Samson

02/20/07

Technician

Date

Inspector

Date

