1. Approving Civil Aviation Authority / Country:	2.	3. Form Tracking Number:
FAA/United States	**Authorized Release Certificate** FAA Form 8130-3, Airworthiness Approval Tag	123546

4. Organization Name and Address:	5. Work Order/Contract/ Invoice Number:
Aviation Instruments Repair Specialists VTBR433V A.I.R.S. / 665 Mokena Dr. #104 Miami Springs, FL 33166 U.S.A. Phone: (305) 887-5600 Fax: (305) 887-3038	R240222

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	TEMPERATURE IND.	WL202EED6	1ea.	AF126/087	REPAIRED

12. Remarks:

REPAIRED in accordance with CMM: 77-20-47 Revision: 15 Date: 1/31/2014

Full details of work carried out per work order no. 123546

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the TEMPERATURE IND. is condidered ready for release to service under EASA Part 145 approval no. EASA EASA.145.5033 .

No applicable A.D. or S.B. Required.

ECCN #9A991D.

13a. Certifies the items identified above were manufactured in conformity to:	14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplish in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
Not Applicable	Not Applicable		VTBR433V
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed)	14e Date (dd/mmm/yyyy):
Not Applicable	Not Applicable	Marshall Garber	21/Aug/2014

User/Installer Responsibilities

It is important to understand that the existance of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1.

Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

Aviation Instruments Repair Specialists

A.I.R.S. / 665 Mokena Dr. #104
Miami Springs, FL 33166
U.S.A.
Phone: (305) 887-5600 Fax: (305) 887-3038
C.R.S. No.: VTBR433V

Work Order: 123546
Date: August/21/2014

Phone:(305) 887-5600
Fax: (305) 887-3038

Sold To:
A J WALTER AVIATION
The Headquarters, Maydwell Ave. Slinfold
West Sussex RH13 0SH, UK

Ship To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 OSH

Part Number: WL202EED6 **Serial:** AF126/087 **Manufacturer:** GE AVIATION
Description: TEMPERATURE IND. Model: WL202EED6
Purchase Order: R240222 **Service Performed:** REPAIRED
Data used: **Manual Number:** 77-20-47 **Revision:** 15 **Date:** 1/31/2014

Teardown/Inspection Data

1. Removal: EGT TIME TO TIME
Inst.: REP

2. Initial Inspection Findings
Appearance: Normal on Visual Inspection **Corrosion:** No Corrosion Noted
Loose or Missing Parts: No Loose or Missing Parts **Physical Damage:** Inductor and Cap
Mod. Level: 1,2,5

3. Teardown
Dissassembly: Normal **Cleaning:** Normal Cleaning
Painting: Normal Painting **Assembly:** Normal Assembly

4. Test
Operation: Operation I/A/W Mfg. Specs **Was Complaint Verified:** Yes
Mods. Completed: None

5. Final
Warranty Accepted: N/A **Final Test and Inspection:** Final Inspection Normal
T.S.O.: TSO **A.T.A.:** 77-20-47 **A.D. S.B.** NO A.D. / S. B. REQUIRED

Work Done: UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, PAINTED, AND ASSEMBLED. REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 77-20-47. WORK BY EYDA DOMINGUEZ. ECCN #9A991D.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work Order No.: 123546

Inspector's Name: Marshall Garber
Certificate No. 2506369

Technician: Eyda Dominguez

Signature: _____ **Date:** **August/21/2014** Form CRS-3