AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number:
FAA/United States		T33468

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110 FAA Repair Station : 68IR700B EASA Reference : EASA.145.6295 Ph: 704-821-4266 Fax: 704-821-4286	**W134300**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	BOX, ATTENDANT GASEOUS OXY	418W1080-2323A	1	NSN	REPAIRED

12. Remarks: REPAIRED In Accordance with CMM 35-21-13 Rev.: 37 Date: JUL/01/2019
The above specified unit was manufactured by: BOEING.

FULL DETAILS OF WORK CARRIED OUT PER
WORK ORDER NUMBER: W134300

COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADS):
N/A

COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs):
N/A

Certifies that the work specified in blocks 11/12 was carried out in accordance with EASA Part-145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.6295

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
- ☐ Non-approved design data specified in Block 12.

14a. ☒ **14 CFR 43.9 Return to Service** ☒ **Other regulation specified in Block 12.**

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			68IR700B
13d. Name (Types or Printed):	**13e. Date (dd/mmm/yyyy):**	**14d. Name (Typed or Printed)**	**14e. Date (dd/mmm/yyyy)**
		ALEXSANDER GARCIA	10/Feb/2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1,it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s)from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases,aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA REPAIR STATION 68IR700B
EASA REFERENCE EASA.145.6295
2617 EXECUTIVE POINT DR.
MONROE, NC 28110
Ph: 704-821-4266 Fax: 704-821-4286
EMail: sam@iconaerospace.com

WORK ORDER
W134300
Date Rcvd : 27/Jan/2020

TEARDOWN REPORT

AJ WALTER AVIATION, LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH130AS UK

Contact: INVOICES / ACCOUNTING
Contact Ph: 44 1403 798000
Contact Fax:

Cust RO#: T33468
P/N: 418W1080-2323A
S/N: NSN
Desc: BOX, ATTENDANT GASEOUS OXY
Mfgr: BOEING.

Manual Loc: BAE-232
ATA: 35-21-13
Rev: 37 **Rev Date: 01/Jul/2019**
Tag Date: 10/Feb/2020

Reason Removed: UNIT RECEIVED FOR BENCH CHECK AS PER O.E.M SPEC'S

FINDINGS

RECEIVING INSPECTION:
VERIFIED UNIT DATA PLATE, UNIT WAS RECEIVED WITH NO SN ON REPAIR ORDER, UNIT IS NOT SERIALIZED, TRACKING NUMBER W134300 (WO#) WILL BE ASSIGNED FOR TRACKING PURPOSES.

PRELIMINARY INSPECTIONS:
FAILED

HIDDEN DAMAGE:
NONE

CONTINUED INSPECTION:
TESTED. FOUND UNIT DIRTY. UNIT REQUIRES DISASSEMBLY AND O-RING.

***CORRECTIVE* ACTION: UNIT CONDITION REPAIRED**
REPLACED O-RING. CLEANED HOSES AND MASK. REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

SB's, AD's, EO's and RMK's:
NONE

CERTIFICATION

Service Performed: [X] **REPAIRED**

MODIFIED TO:

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
1	MS29513-012	O-RING	NE

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: _____ **DATE:** 10/Feb/2020
ALEXSANDER GARCIA

www.ILSmart.com/Optimizer © ILS eBusiness Services, Inc.
Printed by ILS Optimizer

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number:
FAA/United States		T33468

4. Organization Name and Address:		5. Work Order/Contract/Invoice Number:
ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110	FAA Repair Station : 68IR700B EASA Reference : EASA.145.6295 Ph: 704-821-4266 Fax: 704-821-4286	W134300

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	BOX, ATTENDANT GASEOUS OXY	418W1080-2323A	1	NSN	REPAIRED

12. Remarks: REPAIRED In Accordance with CMM 35-21-13 Rev.: 37 Date: JUL/01/2019
The above specified unit was manufactured by: BOEING.

FULL DETAILS OF WORK CARRIED OUT PER
WORK ORDER NUMBER: W134300

COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADS):
N/A

COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs):
N/A

Certifies that the work specified in blocks 11/12 was carried out in accordance with EASA Part-145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.6295

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
- ☐ Non-approved design data specified in Block 12.

14a. ☒ **14 CFR 43.9 Return to Service** ☒ **Other regulation specified in Block 12.**

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			68IR700B
13d. Name (Types or Printed):	**13e. Date (dd/mmm/yyyy):**	**14d. Name (Typed or Printed)**	**14e. Date (dd/mmm/yyyy)**
		ALEXSANDER GARCIA	10/Feb/2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1,it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s)from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases,aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA REPAIR STATION 68IR700B
EASA REFERENCE EASA.145.6295
2617 EXECUTIVE POINT DR.
MONROE, NC 28110
Ph: 704-821-4266 Fax: 704-821-4286
EMail: sam@iconaerospace.com

WO Packing List

Ship Doc : I127434
Shipped : FEB/10/2020
# of Items : 1
Page : 1 of 1

Bill To:
AJ WALTER AVIATION, LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH130AS UK

Ship To:
AJ WALTER AVIATION, LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH130AS UK

Customer	: AJWA1	**Our WO**	: W134300	**Order Date**	: FEB/10/2020
Terms	: Net 30	**Sales Person**	:	**Ship Date**	: FEB/10/2020
FOB	: Monroe, NC	**Cust PO**	: T33468	**AWB #**	: 777725590050
Ship Via	: FEDEX INTL	**Attention**	: ROSE MICKELWRIGHT	**Weight**	: 20
Ship Account	:	**Phone**	: 44 1403 798000	**#Boxes**	: 1
Insure	: N	**Fax**	:	**Dimensions**	: 24 X 12 X 12
Resale	: N/A	**Email**	: accountspayable@ajw-group.com		

Item	Part Number/Description	CD	UM	Qty	B/O	Shipped/Initials
1	418W1080-2323A DESC: BOX, ATTENDANT GASEOUS OXY S/N: NSN	SV	EA	1	0	1 _____

Picture Taken: ☐

FAA REPAIR STATION 68IR700B
EASA REFERENCE EASA.145.6295
2617 EXECUTIVE POINT DR.
MONROE, NC 28110
Ph: 704-821-4266 Fax: 704-821-4286
EMail: sam@iconaerospace.com

WORK ORDER

W134300

Date Rcvd : 27/Jan/2020

TEARDOWN REPORT

AJ WALTER AVIATION, LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH130AS UK

Contact: INVOICES / ACCOUNTING
Contact Ph: 44 1403 798000
Contact Fax:

Cust RO#: T33468
P/N: 418W1080-2323A
S/N: NSN
Desc: BOX, ATTENDANT GASEOUS OXY
Mfgr: BOEING.

Manual Loc: BAE-232
ATA: 35-21-13
Rev: 37 **Rev Date: 01/Jul/2019**
Tag Date: 10/Feb/2020

Reason Removed: UNIT RECEIVED FOR BENCH CHECK AS PER O.E.M SPEC'S

FINDINGS

RECEIVING INSPECTION:
VERIFIED UNIT DATA PLATE, UNIT WAS RECEIVED WITH NO SN ON REPAIR ORDER, UNIT IS NOT SERIALIZED, TRACKING NUMBER W134300 (WO#) WILL BE ASSIGNED FOR TRACKING PURPOSES.

PRELIMINARY INSPECTIONS:
FAILED

HIDDEN DAMAGE:
NONE

CONTINUED INSPECTION:
TESTED. FOUND UNIT DIRTY. UNIT REQUIRES DISASSEMBLY AND O-RING.

CORRECTIVE ACTION: UNIT CONDITION REPAIRED
REPLACED O-RING. CLEANED HOSES AND MASK. REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

SB's, AD's, EO's and RMK's:
NONE

CERTIFICATION

Service Performed: [X] **REPAIRED**

MODIFIED TO:

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
1	MS29513-012	O-RING	NE

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: _____ **DATE:** 10/Feb/2020

ALEXSANDER GARCIA

www.ILSmart.com/Optimizer © ILS eBusiness Services, Inc.