

1. Approving Competent
Authority / Country

UK CAA

2.

AUTHORISED RELEASE CERTIFICATE CAA FORM 1

3. Form Tracking Number

106347836

4. Organisation Name and Address :

Tel: + 33 5 61717700
Fax: + 33 5 61717788

ROCKWELL COLLINS FRANCE
6 AVENUE DIDIER DAURAUT
31700-BLAGNAC-FRANCE

5. Work Order / Contract / Invoice
T42621

6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status / Work
000010	GLU-920 / GLOBAL LANDING UNIT, GLU-920	822-1152-004	1	120536	MODIFIED

12. Remarks


1. Modified & Inspected/Tested referring to Tested Per documentation(s) in Service/Memorandum (see Form Tracking Number in block 3). 2. Modification installed this return: SB GLU-920-34-702. SB GLU-920-34-702 applied this return but not marked on the modification plate in accordance with the service bulletin instructions. Item Numbers refer to numbers on Delivery Document

13a. Certifies that the items identified above were manufactured in conformity to :

- ☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/Authorisation No	14b. Authorised Signature	14c. Certificate/Approval Ref.No
			UK.145.01567
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Charlotte Kaby APPRS 275	01/DEC/2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority /
Country / **Autorité compétente / Pays**
DIRECTION GENERALE DE
L'AVIATION CIVILE
FRANCE

4. Organisation Name and Address :
Nom et Adresse de l'Organisme :

ROCKWELL COLLINS FRANCE
6 AVENUE DIDIER DAURAT
31700-BLAGNAC-FRANCE

AUTHORISED RELEASE CERTIFICATE
Certificat Libérateur Autorisé
EASA FORM 1
Formulaire 1 de l'EASA

5. Work Order / Contract / Invoice
Bon de commande / Contrat / Facture
T 42621

3. Form Tracking Number
N° de repère du Formulaire
106347836

6. Item / Item	7. Description / Description	8. Part No. / N° de pièce	9. Qty / Qté	10. Serial No. / N° série	11. Status / Work / Etat / Travaux
000010	GLU-920 / GLOBAL LANDING UNIT, GLU-920	822-1152-004	1	120536	MODIFIED

12. Remarks
Remarques

1. Modified & Inspected/ Tested referring to Tested Per documentation(s) in Service/Memorandum (see Form Tracking Number in block 3) - 2. Modification installed this return: SB GLU-920-34-702. SB GLU-920-34-702 applied this return but not marked on the modification plate in accordance with the service bulletin instructions.
3. Transport Canada Approval: N° 802-05.
Item Numbers refer to numbers on Delivery Document

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for release or return to service under certificate No R9CY096N

13a. Certifies that the items identified above were manufactured in conformity to :
Certifie que les éléments identifiés ci-dessus ont été fabriqués conformément à :

☐ approved design data and are in condition for safe operation
données de conception approuvées et sont en état de fonctionner en toute sécurité

☐ non-approved design data and are in condition for safe operation
données de conception non approuvées et sont en état de fonctionner en toute sécurité

13b. Authorised Signature
Signature autorisée

13c. Approval/Authorisation No
Numéro d'agrément d'autorisation

13d. Name / Nom

13e. Date (dd mm yyyy) /
Date (jj mmm aaaa)

14a. ☒ Part 145, A.50 Release to Service
Approbation pour remise en service
Selon Partie 145, A.50

14b. Authorised Signature
Signature autorisée

14c. Certificate/Approval Ref. No
N° du Certificat/Agrément
FR.145.0121

14d. Name / Nom
Charlotte Kabay APPRS 275

14e. Date (dd mm yyyy) /
Date (jj mmm aaaa)
01/DEC/2023

USER/INSTALLER RESPONSIBILITIES / Responsabilités de l'utilisateur/installateur
This certificate does not automatically constitute authority to install the item(s).
Ce document ne constitue pas forcément l'autorisation d'installer l(es) item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Quand l'utilisateur/installateur s'assure que son autorité de navigabilité accepte les items libérés par l'autorité de navigabilité mentionnée dans la case 1.
When the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Lorsque l'utilisateur/installateur s'assure que son autorité de navigabilité accepte les items libérés par l'autorité de navigabilité mentionnée dans la case 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.
Les indications portées en cases 13a et 14a ne constituent pas une certification de montage. Dans tous les cas le dossier d'entretien de l'aéronef doit contenir une certification d'installation émise en conformité avec les règlements nationaux par l'utilisateur/installateur avant que l'aéronef puisse voler.

Service Notification: 106347836

Service Memorandum

Customer: AJ WALTER AVIATION LTD

Contract Number: 40481742

Page 1 of 2

Customer P.O. Number: T42621

Cust Reject #:

Govt Incoming Doc #:

Date Equipment Received: 11/15/2023

Repair Station Certificate #:

R9CY096N FR. 145.0121

ROCKWELL COLLINS FRANCE

R9CY096N FR. 145.0121

PO Box 20008

F-31700 BLAGNAC

France

Outgoing Equipment

Incoming Equipment

Aircraft Information

Type : Boeing 757-200

Serial Number : 29309

Tail No : GLSAO

Position :

Removed at Gateway:

Date Unit Removed : 11/09/2023

For Questions Regarding This

Service Work, Please Contact

Customer Service at:

Phone : + 33 61418824

Fax :

Customer Complaint/Instructions

LEASE QUOTE TO TEST, INSPECT AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS TEST. REMOVED IN SERVICEABLE CONDITION FROM A/C REGN: G-LSAO (ex G-ZAPX) MSN 29309 PLEASE RECORD THE COMPONENT TSN 7095:26 CSN 2636 ON YOUR RELEASE CERTIFICATION Unit will be placed into our rotatable pool or general inventory/stock maintained by us. We confirm that it will not be re-exported or otherwise transferred to Cuba, Iran, North Korea, Sudan, Syria, Russia, Belarus, or any region of Ukraine subject to sanctions

Preliminary Inspection Results:

COLLINS SEAL PRESENT. NEED TO APPLY SB GLU-920-34-702 REV 1 TO CURE ETSO MARKING ON IDENT PLATE

NONE.

Was the Complaint Verified? YES

Were There Any Defects Found? NO

Description of What Was Wrong with the Equipment:

UNIT FOR RECERTIFY. NO FAULT IN NVM.

Airworthiness Directives

NO AD's APPLICABLE TO THIS ARTICLE.

Description of Service Work Performed:

APPLIED SB GLU-920-34-702 REV 1 TO CURE ETSO MARKING ON IDENT PLATE. CLEANING. BENCH TEST-OK.

Service Notification: 106347836

Service Bulletins/Mods Installed This Return:

702

Outgoing Service Bulletin Configuration:

1,2,3,7,8,10,11,12,13,14,15,16,17,18,19,20,21,22,25,505,702

This Article Has Been Certified Airworthy On 12/01/2023 By Charlotte Kaby APRS 275 	Preliminary Inspection : 11/28/2023 By Olivier D'Aiatti Hidden Damage Inspection : 11/29/2023 By N / A Service : 11/29/2023 By N / A Final Test : 11/29/2023 By Olivier D'Aiatti Tested Per 1 : 523-0810842 ED. 1 REV. 52 TEMP REV. - Final Inspection : 12/01/2023 By Charlotte Kaby
Defective / Failed Parts Replaced	Circuit Symbol
Part Number	Description