	proving Civil Aviation	2.			Form Tracking Number.
	uthority/Country:	AUTHORIZED RI FAA FORM 8130-3, AIR			720193
Accesso	nization Name and Addres ory Technologies Corp pair Station Certificate	s. oration, 41 Mercedes Way Ur			5. Work Order, Contract, or Invoice Number:
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ACTUATOR, ROTARY	692D100-15	1	3058B	OVERHAULED
PART NO	UMBER CHANGED TO ory Technologies Cance with EASA Part	REFLECT IMPLEMENTATION orporation certifies that the 145 and with respect to the 145 ance Certificate Number	N OF SERVICE e work spec hat work, th	E BULLETIN. cified in Blocks 11 a e aircraft compone	and 12 was performed in ent is considered ready for release
☐ Approv		were manufactured in conformity to: a condition for safe operation. ied in Block 13	Certifies that 11 and des Code of Fe	at unless otherwise speci scribed in Block 12 was	orice Other regulation specified in Block 12 ified in Block 12, the work identified in Block accomplished in accordance with Title 14, 13 and in respect to that work, the items are
13b. Auth	orized Signature:	13c. Approval Authorization No:	14b. Autho	rized Signature:	14c. Approval/Certificate No: Y4AR039O
13d. Nam	e (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name	(Typed or Printed): Raheel Khan	14e. Date (dd/mmm/yyyy): 04/MAR/2022
		User/Insta	aller Respon	nsibilities	
Where the the country the airwort	user/installer performs wo y specified in Block 1 it is hiness authority of the cou	ork in accordance with the national essential that the user/installer ensortry specified in Block 1.	regulations of a sures that his/he	an airworthiness authority er airworthiness authority all cases, aircraft mainte	by to install the part/component/assembly. If different than the airworthiness authority of accepts parts/components/assemblies from enance records must contain an installation
certification	n issued in accordance wit	h the national regulation by the use	er/installer befor	re the aircraft may be flow	vn. NSN:0052-00-012-9005

n

accessory Technologies Corporation 41 Mercedes Way Unit #34 Edgewood, NY 11717 http://www.atcny.com FAA CRS: Y4AR0390 EASA: 145.4014

631-753-2282 (Phone) 631-753-2407 (Fax)

Customer Service Report

Work Order #:

720193

Page: 1

CUSTOMER: A J WALTER (AVIATION) LTD

REF #: T36371

TAIL #: F-GSPV

ATA: 52-34-02

OEM: EATON

DESCR: ROTARY ACTUATOR - LARGE CARGO DOOR P/N RECEIVED: 692D100-13

P/N SHIPPED: 692D100-15

S/N: 3058B

OPEN DATE: 1/24/2022

WARRANTY No

CONTAINER: N/A

WORK REQUESTED: Repair

WORK PERFORMED: Overhauled and Modified

REASON FOR REMOVAL: Unknown

CONFIRMED: Yes.

INCOMING INSPECTION: O.K. Externally

TEARDOWN INSPECTION: No-Back Assy damaged. Ring damaged. Seals worn. Misc hardware need replacement. .

WORK PERFORMED: Disassembled Unit. Performed required inspections. Replaced all material as required. Reassembled and tested. All work performed I/A/W the latest Eaton CMM and AD US-2015-12-11. O.K. to return to service.

NOTE: Part number change reflects implementation of service bulletin 692D100-52-4.

PN	Description	Qty Issued	CD
692C137-1	RING SWAGE	1.00	NE
692C193-1	PLATE, IDENTIFICATION	1.00	NE
692D190-5	NO BACK ASS	1.00	NE
692SA146-1	SEAL TEFLON	1.00	NE
999803-02	PLATE COMPLIANCE	1.00	NE
MOD TO -15	MOD TO -15	1.00	NE

AUTHORIZED SIGNATURE:

DATE:

Mar/04/2022

Form ATC-002

Rev 2 12/14/20