

1. Approving Civil Aviation
Authority/Country:

2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

FWO30113

4. Organization Name and Address:

Repair Station: 9QAR940B

VSE Aviation Services, Inc.
3361 Enterprise Way, Miramar, FL 33025, Fax: 954/430-6601, 954/430-6600

5. Work Order/Contract/Invoice
Number:

FWO30113 / R399508

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1. BLEED AIR VALVE

1853M12P04

1.00

GRTU9248

OVERHAULED

12. Remarks: This item was OVERHAULED I/AW Manual # CMM 75-21-27, Revision # 3 Revision Date 4/22/2020

NO APPLICABLE AD'S AND NO SB'S INSTALLED.

TSO:00:00.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

FRANCISCO A. BAUTISTA

21-Dec-2022

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL 33025
Fax: 954/430-6601
954/430-6600

Customer: **AJW001 / AJ WALTER AVIATION**
Cust RO#: **R399508**
Mfg: **HONEY**
Outgoing: **1853M12P04 / BLEED AIR VALVE**

WORK ORDER FORM 100



Page No. 1

Step: SH-SHIPPING
Department: Shop FLA
Location: FLA FUE
Warranty Code: 00
Goodthru AD#: **FAA CRS No: 9QAR940B**
Work Order #: FWO30113
NO PMA PARTS
S/N: GRTU9248

Incoming P/N: 1853M12P04	Incoming S/N: GRTU9248	Incoming Work Req: BC
Repair Manuals: F0313		
Tools: FK0313		

REASON FOR REMOVAL:	Date Recvd: 8/31/2022	Date Recrd: 9/16/2022	Date Estmd: 9/16/2022
BENCHCHECK			
PRELIMINARY INSPECTION: DATE: 9/13/22 INSPECTOR: FAB			
PN AND SN VERIFIED PER R/O AND ID PLATE. THIS UNIT WAS RECEIVED IN POOR CONDITION			
PRE TEST (Yes/No): Y DATE: 9/13/22 INSPECTOR: FAB			
UNIT FAILED TEST DUE TO LEAKAGE			
HIDDEN DAMAGE: NN			

TEARDOWN FINDINGS:	THIS UNIT WAS DISASSEMBLED, CLEANED AND INSPECTED IAW MFG SPECS. ALL PACKING, VARIOUS SEALS, BEARING, SETSCREW, CLIP, NUT AND RETAINER WAS FOUND DEFECTIVE AND REQ'S REPLACEMENT THIS UNIT WILL BE OH IAW MFG SPECS OH QUOTE		
TECHNICIAN: DJM	DATE: 9/13/22	INSPECTOR: FAB	FINAL INSPECTION BEFORE ASSEMBLY DATE: 12/21/22 INSPECTOR: FAB

CORRECTIVE ACTION:	THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, FUNCTIONALLY TESTED, AND OVERHAULED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.		
TECHNICIAN: DJM	DATE: 12/21/22	INSPECTOR: FAB	MODIFICATION/SERVICE BULLETINS: NO APPLICABLE AD'S AND NO SB'S INSTALLED.
TEST DATA USED: TSO: 00:00			
ATA: 75-21-27 REV#3 22APR2020			

WORK ORDER FORM 100

Page No. 2

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600



FAA CRS No: 9QAR940B

Work Order #: FWO30113

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA FUE

Customer: **AJW001 / AJ WALTER AVIATION**

Cust RO#: **R399508**

Mfg: **HONEY**

Outgoing: **1853M12P04 / BLEED AIR VALVE**

*****NO PMA PARTS*****

S/N: GRTU9248

Warranty Code: 00

Goodthru AD#:

Incoming P/N: 1853M12P04

Incoming S/N: GRTU9248

Incoming work Req: BC

Outgoing Work Req: OVERHAULED

Test Technician: DJM

Date: 12/21/22

Final Inspection: FAB

Date: 12/21/22

ADDITIONAL COMMENTS:

N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by **FRANCISCO A. BAUTISTA**



Date: 12/21/2022 3:49:14 PM