

1. Approving Civil Aviation Authority / Country: FAA/United States		2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: 123322	
4. Organization Name and Address: Aviation Instruments Repair Specialists A.I.R.S. / 665 Mokena Dr. #104 Miami Springs, FL 33166 U.S.A. Phone: (305) 887-5600 Fax: (305) 887-3038				5. Work Order / Contract / Invoice Number: R239916	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	TEMPERATURE IND.	WL202EED6	1ea.	AB529/075	REPAIRED
12. Remarks: REPAIRED in accordance with 77-20-47 Revision 15. Full details of work carried out per work order no. 123322 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the TEMPERATURE IND. is considered ready for release to service under EASA Part 145 approval no. EASA.145.5033. No applicable A.D. or S.B. Required. ECCN #9A991D.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature: Not Applicable	13c. Approval/Authorization No.: Not Applicable	14b. Authorized Signature: 		14c. Approval/Certificate No.: VTBR433V	
13d. Name (Typed or Printed): Not Applicable	13e. Date (dd/mm/yyyy): Not Applicable	14d. Name (Typed or Printed): Marshall Garber		14e. Date (dd/mm/yyyy): 23/Jul/2014	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

Aviation Instruments Repair Specialists

A.I.R.S. / 665 Mokena Dr. #104

Miami Springs, FL 33166

U.S.A.

Phone: (305) 887-5600 Fax: (305) 887-3038

C.R.S. No.: VTBR433V

Work Order: 123322

Date: July/23/2014

Phone: (305) 887-5600

Fax: (305) 887-3038

Sold To:

A J WALTER AVIATION

The Headquarters, Maydwell Ave. Slinfold

West Sussex RH13 0SH, UK

Ship To:

A J WALTER AVIATION LIMITED

THE HEADQUARTERS MAYDWELL AVENUE

SLINFOLD, WEST SUSSEX RH13 0SH

Part Number: WL202EED6

Serial: AB529/075

Manufacturer: GE AVIATION

Description: TEMPERATURE IND.

Model: WL202EED6

Purchase Order: R239916

Service Performed: REPAIRED

Data used: Manual Number: 77-20-47 Revision: 15 Date: 1/31/2014

TearDown/Inspection Data

1. Removal: INOP

Inst.: REP

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Loose or Missing Parts: No Loose or Missing Parts

Mod. Level: 1,2,5

Corrosion: No Corrosion Noted

Physical Damage: Lamps and Calibration

3. Teardown

Disassembly: Normal

Painting: Normal Painting

Cleaning: Normal Cleaning

Assembly: Normal Assembly

4. Test

Operation: Operation I/A/W Mfg. Specs

Mods. Completed: None

Was Complaint Verified: Yes

5. Final

Warranty Accepted: N/A

T.S.O.: TSO

Final Test and Inspection:

A.T.A.: 77-20-47

Final Inspection Normal

A.D. S.B. NO A.D. / S. B. REQUIRED

Work Done: UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, PAINTED, AND ASSEMBLED. REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 77-20-47. WORK BY EYDA DOMINGUEZ. ECCN #9A991D.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 123322

Inspector's Name: Marshall Garber

Certificate No. 2506369

Technician: Eyda Dominguez

Signature: _____

Date: July/23/2014

Form CRS-3