

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO114477	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: R387938-1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Air Traffic Service Unit	LA2T0G20503B040	1.00	2T0000300	REPAIRED
12. REMARKS UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 46-21-34 REV:09 FEB 23/2018 FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN REPORT.					
PRINTED FROM ELECTRONIC FILE					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12			
13b. Signature:		13c. Approved Organization Number		14b. Signature	
13d. Name (Typed or Printed):		13e. Date		14c. Approval Organization Number 33-12	
				14d. Name (Typed or Printed) Alii Abdeljalil	
				14e. Date (dd/mm/yyyy) 22/Nov/2021	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW[®] TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO114477

Date Printed: 11/22/2021

Customer RO: R387938-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: Air Traffic Service Unit

Phone:

P/N: LA2T0G20503B040

Qty: 1

Email:

S/N: 2T0000300

Mfg: AIRBUS OPERATIONS

TSN: UNK

TSO: UNK

TSR: 0

CSN: UNK

CSO: UNK

CSR: 0

P/N Out: LA2T0G20503B040

S/N Out: 2T0000300

Symptoms:

CODE: REPAIR

DETAILS: VHF DATALINK FAULT.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: UNIT FAIL THE ACCEPTANCE TEST:
ARINC BOARD FAIL

CODE: REPAIR

DETAILS: The following repair(s) will be performed:
UNIT NEEDS TO BE REPAIRED:
ARINC BOARD NEEDS TO BE REPLACED

Corrective Actions:

CODE: REPAIRED

DETAILS: UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 46-21-34 REV:09 FEB 23/2018