

# TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: (305) 887-5600 Fax: (305) 820-0931

C.R.S. No.: VTBR433V

Work Order: 163447

Date: February/26/2021

**Sold To:**

MULTIVERSE AEROSPACE

1791 BLOUNT RD #604 POMPANO BEACH, FL 33069

**Ship To:**

MULTIVERSE AEROSPACE

1791 BLOUNT RD #604 POMPANO BEACH, FL. 33069

**Part Number:** 6670M2230

**Serial:** BC22

**Manufacturer:** ENDEVCO

**Description:** AVM SIGNAL CONDITION

**Model:**

**Purchase Order:** R425

**Service Performed:** No Work Done

**Data used:** Manual Number: 77-30-25

**Revision:** 0

**Date:** 12/20/2018

## Teardown/Inspection Data

**1. Removal:** SEE RO

**Inst.:** REPAIRED

**2. Initial Inspection Findings**

**Appearance:** Not Applicable

**Loose or Missing Parts:** Not Applicable

**Mod. Level:** 1,2

**Corrosion:** Not Applicable

**Physical Damage:** Not Applicable

**3. Teardown**

**Dissassembly:** Not Applicable

**Painting:** Not Applicable

**Cleaning:** Not Applicable

**Assembly:** Not Applicable

**4. Test**

**Operation:** Not Applicable

**Was Complaint Verified:** No

**Mods. Completed:** Not Applicable

**5. Final**

**Warranty Accepted:** N/A

**Final Test and Inspection:** Not Applicable

**T.S.O.:**

**A.T.A.:** 77-30-25

**A.D. S.B.** Not Applicable

**6. Work Done**

No work performed in unit. Returned as is.!!

\*\*\* No Work Performed \*\*\*

\*\*\* No Work Performed \*\*\*

Work Order: 163447

**Inspector:** Not Applicable

**Technician:** Not Applicable

**Signature:**

**Date:** February/26/2021

**Form:** CRS-3