

1. Approving Competent Authority/Country CAA/UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 86916911-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350563415 PO: T42208 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	Engine Vibration Monitoring Unit	241-246-022-004	1	0185	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. Applicable Technical Docs: CMM 77-32-09 REV.5 DATED NOV 24/2022 For work carried out, refer to Service Breakdown Report for Service Order 45460328							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12				14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service			
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  J. Mettraux		14c. Certificate/Approval Ref No. UK.145.01715	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name JEROME METTRAUX		14e. Date (dd mmm yyyy) 13OCT2023	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority/Country FEDERAL OFFICE OF CIVIL AVIATION (FOCA) SWITZERLAND		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 86916911-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350563415 PO: T42208 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	Engine Vibration Monitoring Unit	241-246-022-004	1	0185	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate no. VM8Y694J. Applicable Technical Docs: CMM 77-32-09 REV.5 DATED NOV 24/2022 For work carried out, refer to Service Breakdown Report for Service Order 45460328							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12				14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service			
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  VNI - CS COA - 07 J. Mettraux		14c. Certificate/Approval Ref No. CH.145.0251	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name JEROME METTRAUX		14e. Date (dd mmm yyyy) 13OCT2023	

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TEST REPORT

Subject: ACCEPTANCE TEST REPORT
Item: Engine Vibration Monitoring Unit
Type: EVM-246
MFR: S3960
PNR: 241-246-022-004
Cust. PNR: CMS 69 958 116 00
Mod. Record:
SER: 000185
DMF: 081997
Applicable Doc.: ATP-1206-04 rev 01
Software PNR: 299-500-000-015
Database PNR: 299-517-500-002
AU SER: AC85214
Operator: J.Chassot
Test Result: PASS
Started: 06 Oct 2023 09:30:53
Finished: 06 Oct 2023 09:53:11
Report generated: 06 Oct 2023 09:53:11
Report Location: \\ngts\atr\atp1206_04r01_evm246/P-000185-20231006-095437.html
GTS Hostname: gtsxp0011
Comment:

Signature:

Department Approval:

Date of Approval:

06 OCT. 2023

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page 1 of 1
Date 09.10.2023
Service notification 350563415
Meggitt quality notification
Service order/Report No 45460328
Sales order 9953491026
Customer PO# T42208
Customer quality ref
Customer Part#

Equipment serviced here

Item	Part number/ Description	Serial number	Mod Status/Revision
1	241-246-022-004 EVM 246 - Engine Vibration Monitoring Unit Applicable Technical Docs:	0185	- / - CMM 77-32-09 REV.5 DATED NOV 24/2022

Failure / complaint (as reported by customer)

For test, Please quote to repair if it fails test.
A/C: @@CS-TTD@@
EASA/FAA / CAA

Findings

Seals ok, no major damage was notified at reception.
Self test pass.
Accel config ok.
Unit works within specification.
No fault found.

Materials

Item	Qty	UOM	Part Number	Batch Number	Description	Cond
------	-----	-----	-------------	--------------	-------------	------

Work performed

Incoming Inspection (Admin)
Preliminary hidden damage inspection
SB/SIL/AD status check performed
Visual Inspection
Check connectors condition
Read & Analyze Internal Memory
Incoming ATP Technician
Incoming ATP Test System
Tested & Inspected IAW CMM listed above
Final ATP Technician
Final ATP Test System
Final FOD check
Administration

