AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

1. Approving National Aviation Authority/Country: **FAA/UNITED STATES**

2.

3. Form Tracking Number: **121306362**

4. Organization Name and Address:
Precision Aero Technology
3333 East Spring Street
Long Beach, CA 90806-6826

FAA CERTIFICATION # DQ3R458L

Phone: 562-595-6055
FAX: 562-595-1815

5. Work Order, Contract, or Invoice Number: **121306362**
Cust Ref: T13173

6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	**GND TEST ENABLE MODULE**	**233U4215-1**	N/A	1	**D00193**	**INSPECTED**

13. Remarks:
31-12-05 Rev:2 11/4/2010
A GENERAL DESCRIPTION OF THE WORK PERFORMED IS IN THE ATTACHED WORK ORDER DOCUMENT, UNDER THE PART DESCRIPTION LISTED IN BLOCKS 6,7,8,10 AND 11 AS APPLICABLE. A COMPLETE DESCRIPTION OF WORK PERFORMED IS ON FILE AT THE ABOVE REFERENCED ORGANIZATION UNDER THE WORK ORDER AND SYSTEM TRACKING REFERENCE NUMBER INDICATED IN BLOCKS 3 AND 5. NOTICE: An Airworthiness Directive may apply to the articles(s) described hereon. The installer is responsible for ensuring complete compliance with any applicable Airworthiness Directives.

Precision Aero Technology certifies that the work specified in block 12 and 13 was performed in accordance with EASA part 145 and with respect to that work, the aircraft component is considered ready for release to service under EASA part 145 Approval Number EASA.145.4052.

14. Certifies the items identified above were manufactured in conformity to:
- ☐ Approved design data and are in condition for safe operation
- ☐ Non-approved design data specified in Block 13.

15. Authorized Signature:

16. Approval/Authorization No.:

17. Name (Typed or Printed):

18. Date (m/d/y):

19. ☑ 14 CFR 43.9 Return to Service ☑ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

20. Authorized Signature:

21. Approval/Certificate Number: **DQ3R458L**

22. Name (Typed or Printed): **ERNESTO FONTANILLA**

23. Date (m/d/y): Jul/23/2013

User/Installer Responsibilities

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft maybe flown.

*Installer must cross check eligibility with applicable technical data.

Precision Aero Technology

3333 East Spring Street
Long Beach, CA 90806-6826
Phone: 562-595-6055
FAX: 562-595-1815

FAA # DQ3R458L ARINC: LGBGHXD

Work Order

DATE RECEIVED	WORK ORDER NO.
06/24/2013	121306362
DATE COMPLETED	CUSTOMER ORD NO.
07/23/2013	T13173

ROUTINE

BILL TO	SHIP TO
A1414 **AJ WALTER AVIATION LTD** THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST RH13 0SH UNITED KINGDOM	A1414S AJ WALTER AVIATION LTD LOGISTICS CENTER, THE BUSINESS PARK, MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0SH UNITED KINGDOM

Action Requested	Unit Number	Description	Serial Number
REPAIR AS NECESSARY	233U4215-1	GND TEST ENABLE MODULE	D00193
Aircraft Number	**Customer Part No.**		**Manual No.**
VH-OJR			31-12-05
Aircraft Position	**Last Repair Station**	**T S O**	**Manual Date/Loc**
			11/04/2010 AL-1758

REASON FOR REMOVAL	SPECIAL INSTRUCTIONS
PLEASE INSPECT AND REPAIR AS NECESSARY.	T & M

Service Performed **Detailed Service Report**

Incoming Inspection:

UNIT RECEIVED IN FAIR CONDITION.

Shop Evaluation:

PRELIMINARY INSPECTION SHOWS NO OBVIOUS PROBLEM.

Work Accomplished:

INSPECTED UNIT, CLEANED FRONT PANEL, CONNECTOR AND SWITCH ASSEMBLY. PERFORMED FUNCTIONAL TEST AND VERIFIED TO MEET THE TECHNICAL SPECIFICATIONS. THE ABOVE MENTIONED WORK WAS PERFORMED I.A.W. C.M.M. 31-12-05.

Service Performed	Warranty	Removal Reason Confirmed
I INSPECTED	☐ Accepted ☐ Denied ☒ N/A	☐ Yes ☐ No ☒ N/A

TECHNICIAN	INSPECTOR	8130 REFERENCE
LAURENTIU GEORGESCU	ERNESTO FONTANILLA	69820