

1. Approving Competent Authority/ Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number 000000097891	
4. Organisation Name and Address : NORDAM Europe Limited 3, Hawtin Park BLACKWOOD Gwent NP12 2EU UNITED KINGDOM						5. Work Order/ Contract/ Invoice 500282474 BOG/PO/3479	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/ Work		
0001	REVERSER, CFM56-7 RH	315A2295-220	1	2502	Overhauled		
12. Remarks OVERHAULED I.A.W BOEING CFM56-7 CMM 78-31-37 REV 53 DATED 1st JULY 2023, CMM 78-31-24 REV 47 DATED 1st NOV 2022, 737-800 SRM CHAP 54 REV 79 DATED 10th JULY 2023 AND 737-600/700/800 AMM REV 81 DATED 15th JUNE 2023 AD / SD STATUS MAINTAINED AS RECEIVED AND THE REVERSER IS COMPLIANT WITH ALL MANDATORY AD's / SB's (REFER TO COMPLIANCE LOG) REPAIRS ACCOMPLISHED:- CMM 78-31-37 – ASSEMBLY, TEST AND FAULT ISOLATION OP 2B (1-2) AND OP 3E (1-8), CMM 78-31-24 - ASSEMBLY, REP 1-1, REP 2-1 2C (2f), REP 2-1 2D (2f), REP 2-1 (5C), REP 2-6 (2B), REP 3-2, REP 4-2 737-800 SRM 54-30-01 REP 6 (4A) 737 600/700/800 AMM 78-31-02-400-802 3H (8-9) See attached continuation sheet for Block 12 secondary supportive information							
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation <input type="checkbox"/> Non approved design data specified in Block 12.				14a. <input checked="" type="checkbox"/> Part - 145.A.50. Release to Service <input type="checkbox"/> Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature		13c. Approval/ Authorisation Number		14b. Authorised Signature  NA243		14c. Certificate / Approval Ref No. EASA.UK.145.00530	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name James Puxty		14e. Date (dd mmm yyyy) 04 SEP 2023	
USER/ INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

ORIGINAL (STAMPED GREEN)

THIS IS AN ORIGINAL
RELEASE CERTIFICATE

Form Tracking Number	Work Order/ Contract/ Invoice	Description	Part No	Serial/ Batch No
000000097891	500282474 BOG/PO/3479	REVERSER, CFM56-7 RH	315A2295-220	2502

Continuation Sheet

FOR PREVIOUS WORK ACCOMPLISHED ON THIS REVERSER REFER TO ATTACHED EASA FORM 1 TRACKING No 96725 AND CAA/UK FORM 1 TRACKING No 96726
SEE ATTACHED FORM NEL-F-055 ISS 07 CARRY FORWARD SHEET FOR CUSTOMER INSTRUCTIONS



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	1 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH				
Serial No:	2502	Batch:	0003874896		Equipment: 4000564877

Document	Rev	Rev Date	Description	Compliance
AD 2019-18-03 (EASA)	IR	03 OCT 2019	EASA HAS DUPLICATED THIS AD	N/A (Deferred)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2019-18-03	IR	03 OCT 2019	EXHAUST-BOEING COMPANY	N/A (Deferred)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2013-08-01	IR	10 JUN 2013	TO DETECT AND CORRECT DAMAGE TO THE FIRE SEALS	Previously Complied With
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2012-05-02	00	10 MAY 2012	TO DETECT AND CORRECT HEAT DAMAGE TO THE INNER WALL OF THE THRUST REVERSER	N/A (Not specific to AC or PN)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2012-02-14	00	19 MAR 2012	TO PREVENT A FIRE IN THE FAN COMPARTMENT FROM MIGRATING THROUGH A SEAL IN THE THRUST REVERSER ACTUATOR COMPARTMENT	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	2 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			
Serial No:	2502	Batch:	0003874896	Equipment: 4000564877

Document	Rev	Rev Date	Description	Compliance
SL 78-066	00	04 MAY 2009	THRUST REVERSER HALF INTERCHANGEABILITY BETWEEN ENGINE POSITIONS	Previously Complied With
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
SB 78-1088	01	26 JUN 2013	THRUST REVERSER INNER WALL INSPECTION AND Repair	N/A (Not specific to AC or PN)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
SB 78-1086	02	31 OCT 2013	INSPECTION OF THE FIRE SEAL AND INSTALLation of a New Fire Seal Bracket on the Thrust Reverser	Previously Complied With
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
SB 78-1085	01	16 DEC 2011	CHANGE TO THE INSULATION BLANKETS ON THE Thrust Reversers	Previously Complied With
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	3 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			
Serial No:	2502	Batch:	0003874896	Equipment: 4000564877

Document	Rev	Rev Date	Description	Compliance
SB 78-1082	01	26 JUN 2013	INSTALLATION OF A COOLING HOLE AND BUSHing, Apply Sealant and Install Flange Insulation Assemblies on the Thrust Reversers	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	4 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2102-174 / WALL, DUCT, INR RH CFM56-7				
Serial No:	N/A-00000000173417	Batch:	0004189593	Equipment: 4000564893	

Document	Rev	Rev Date	Description	Compliance
SB 78-1088	01	26 JUN 2013	THRUST REVERSER INNER WALL INSPECTION AND Repair	N/A (Not specific to AC or PN)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2012-05-02	00	10 MAY 2012	TO DETECT AND CORRECT HEAT DAMAGE TO THE INNER WALL OF THE THRUST REVERSER	N/A (Not specific to AC or PN)
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
AD 2013-08-01	IR	10 JUN 2013	TO DETECT AND CORRECT DAMAGE TO THE FIRE SEALS	Previously Complied With
Additional Information:				

Document	Rev	Rev Date	Description	Compliance
SB 78-1082	01	26 JUN 2013	INSTALLATION OF A COOLING HOLE AND BUSHing, Apply Sealant and Install Flange Insulation Assemblies on the Thrust Reversers	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	5 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2801-1 / ACTUATOR, LOCKING CFM56-7 DEV				
Serial No:	A0042533	Batch:	0004189594		Equipment: 4000564894

Document	Rev	Rev Date	Description	Compliance
AD 2019-18-03	IR	03 OCT 2019	EXHAUST-BOEING COMPANY	N/A (Deferred)
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	6 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	315A2500-30 / TRANS COWL, CFM56-7 RH			
Serial No:	N/A-00000000173410	Batch:	0004178689	Equipment: 4000564899

Document	Rev	Rev Date	Description	Compliance
SL 78-066	00	04 MAY 2009	THRUST REVERSER HALF INTERCHANGEABILITY BETWEEN ENGINE POSITIONS	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	7 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-36 / VANE, CASCADE CFM56-7			
Serial No:	0285	Batch:	0004189566	Equipment: 4000565012

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	8 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-38 / VANE, CASCADE CFM56-7				
Serial No:	0285	Batch:	0004189567		Equipment: 4000565013

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	9 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-24 / VANE, CASCADE CFM56-7				
Serial No:	0305	Batch:	0004189568		Equipment: 4000565014

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	10 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-39 / VANE, CASCADE CFM56-7			
Serial No:	0285	Batch:	0004189569	Equipment: 4000565015

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	11 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-44 / VANE, CASCADE CFM56-7				
Serial No:	0571	Batch:	0004189570	Equipment: 4000565016	

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				



Compliance Log - Results

Ref Doc:	500282474	Customer:	0001001128 - BBAM LLC	Page	12 of 12
Part No / Desc:	315A2295-220 / REVERSER, CFM56-7 RH			Cert#:	000000097891
Serial No:	2502	Batch:		Aircraft:	null
				Printed On:	04 SEP 2023

Part No / Desc:	S315A200-26 / VANE, CASCADE CFM56-7			
Serial No:	0284	Batch:	0004189571	Equipment: 4000565017

Document	Rev	Rev Date	Description	Compliance
SB 78-1076	01	12 MAR 2010	REPLACEMENT OF CASCADE ASSEMBLIES	Previously Complied With
Additional Information:				