

1. Approving Civil Aviation
Authority/Country:
FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
200108

4. Organization Name and Address:

Galaxy International, Inc.
1658 S Litchfield Rd, Hangar 18
Goodyear, AZ 85338

CRS: G0XR924Y
Phone: 623-882-2783
Fax: 623-882-2790

5. Work Order/Contract/Invoice Number:

010590

6. Item:

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 IGNITION EXCITER

3876195-9

1

060218071749

TESTED

12. Remarks:

TESTED REFERENCE 49-41-21, REVISION 5, AUGUST 31, 2018.
FULL DETAILS HELD ON W/O: 200108

Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.5645

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.

Non-Approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name: (Typed or Printed)

13e. Date (m/d/y):

14d Name: (Typed or Printed)

14e. Date (dd/mm/yyyy):

CHRISTOPHER OLGIN

20/MAR/2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Galaxy International, Inc.
1658 S. LITCHFIELD ROAD
HANGAR 18
GOODYEAR, AZ 85338
USA
Ph: 623-882-2783, Fax: 623-882-2790

Tear Down/Inspection

Work Order #: 200108

Date Printed: 3/20/2020

Time: 2:15:53 PM

Page: 1

To:
SETNA IO
2900 W. CHICAGO AVE.
CHICAGO, IL 60622
USA

Ship To:
SETNA IO
2900 W. CHICAGO AVE.
CHICAGO, IL 60622
USA

Ref #: 010590

Phone #: 312-549-4459

Fax #:

Email: michael@setnaio.com

Code: Si1

Site:

PN: 3876195-9

Descr: EXCITER

Qty: 1

Station:

Make:

Model:

Mfg: _

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

Voltage
Panel Type

Color
.....

Color To Be
.....

Engine Number:
Tail Number:

Serial Numbers: 060218071749

Notes: NO WARRANTY ON TEST ONLY

Symptoms:

INSPECTION FINDINGS

P/N VERIFIED
NOTED S/N DISCREPANCY ON RO
UNIT PASSED TEST

Faults:

NO FAULTS

Corrective Actions:

TEST

TESTED UNIT REFERENCING 49-41-21, REVISION 5, AUGUST 31, 2018
DATE OF CERTIFICATON: MARCH 20, 2020