

AUTHORISED RELEASE CERTIFICATE


EASA FORM 1

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany	2.	3. Form Tracking Number DB 90482820 1/1
---	-----------	--

4. Organisation Name and Address:  AIRBUS AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany	5. Work Order/Contract/Invoice W30467
---	--

6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	CIDS FWD.ATTND.PNL.	Z131H0072114	1	131H00000316	MODIFIED

12. Remarks: see Maintenance Report No.1026894 Work performed as per: C.M.M. 23-74-12 Rev.11 Dec-05-2014 and SB Z131H-23-103 Rev.01 Jun-11-2014. work accomplished: OCT-06-2015 Amendment:-1,2	The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.
--	--

13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature:	13c. Approval/Authorisation Number:	14b. Authorised Signature: 	14c. Certificate/Approval Ref.No.: DE.145.0286
13d. Name:	13e. Date (dd/mm/yyyy):	14d. Name: Straub	14e. Date (dd/mm/yyyy): 08.Oct.2015

1 国家 Country China	2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness	3 证书编号 Certificate Ref. No.
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		DB 90482819

4 单位 Organization	AIRBUS AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany	
	Plant Werk	Buxtehude
	5 工作单/合同单/货单 Work Order/Contract/Invoice	W30467

6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
0001	CIDS FWD.ATTND.PNL.	Z131H0072114	APPLICABLE TO MULTIPLE TYPES	1	131H00000316	MODIFIED

13 备注 Remarks

see Maintenance Report No.1026894 Work performed as per: C.M.M. 23-74-12 Rev.11 Dec-05-2014 and SB Z131H-23-103 Rev.01
Jun-11-2014, work accomplished: OCT-06-2015 Amendment:-1,2

14 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该 产品(出口产品)符合经批准的型号设计资料 and 进口国提出的专门要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.	15 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例和进口国 通知的特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)
---	---

16 批准人签名 Signature	18 批准日期 Date	19 中国民航总局授权 Issued by or on behalf of the CAAC
	08.Oct.2015	

17 批准人姓名 (打印的) Name(Printed)	Straub DA_K_6	F04900446
---------------------------------	---------------	-----------

* 参阅产品目录详细查找适用性
Cross-check eligibility for more details with parts catalogue

批准放行证书/适航批准标签

AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG

使用者/安装者职责

USER/INSTALLER RESPONSIBILITIES

- (1) 必须明确：本文件并不批准零件/组件/部件可以装到有关产品上。
- (2) 当使用者/安装者使用的是所在国适航当局的条例，而不是本表第1项中所指国家适航当局的条例时，使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
- (3) 表中第14项、第15项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航条例颁发的安装批准放入维修记录中。

- (1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
- (2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
- (3) Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

MAINTENANCE ORDER Activity Category: V Maintenance Number: 1026894 		Customer		Part Number		Z131H0072114		Serial No SPEC2000		131H00000316		Amd		-1	
		AJW		Description		CIDS FWD.ATTND.PNL.		Quantity		1		Repair-Station		BUX	
Customer Order		Cust. Order Date		21.09.2015		Work Order		1026894		Work Order Date		25.09.2015		Prio	
ROUTINE		Required Activities:		Test		Repair		Modify		Inspection		Scrap		Overhaul	
Reason for Return		SCREEN GOES BLANK INTERMITTENTLY PLEASE MOD AS PER SB Z131H-23-103													
Operator		Removal Date		AC-Reg		TC-OCC		AC Type		A330		Station		UKN	
OHY		Release Certificate		AAC038/EDUAL		Warranty		X		Chargeable					
Operators Man		OEM-Man		O.E.M.-M		Aviation Device		YES		Package		OK			
Department:		ECYSI		Phone:		040-43 68270									
MAINTENANCE REPORT Preliminary Inspection/HDI: YES Pre-Strip-Test: YES Cond. elec.: BAD Cond. SW: OK Cond. mech.: OK BITE: N/A Missing Part: NO															
Findings: The unit amendment label was marked with a wrong number extension. After deeper investigation we detected that the unit must be marked with amendment "-1", because of a mainboard replacement in past, and not with amendment "-2 for the DC/AC power inverter modification. Today the display backlight power inverter was intermittent faulty. Because of no longer available spares, now a modification to amd: -1,2 as per SB Z131H-23-103 is necessary for repair. The unit had some small scratches with no effect on further function.															
Remarks: Work performed as per: C.M.M. 23-74-12 Rev.11 Dec-05-2014 and SB Z131H-23-103 Rev.01 Jun-11-2014.															
Work performed: Preliminary- and hidden damage inspection performed. Unit modified to amd: -1,2 as per SB Z131H-23-103. Acceptance test successfully performed.															
Final Condition PN_After: Z131H0072114 SN_After: 131H00000316 AMD_After: -1,2 Tested: X Repaired: X Modified: X Modified internal: Cond as is Scrapped: Overhauled QA-Inspected:															
Work performed staff				Work performed department				Work performed date				08. Okt. 2015 			
Sperhake				ECYS3				06.10.2015							