

FAA/UNITED STATES

# AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:  
**242029**

4. Organization Name and Address:

Aero Accessories & Repair, Inc.  
FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300,

FAA Approval Holder: 77AR783B

5. Work Order/Contract/Invoice  
Number:  
**57763**  
**T41336**

6. Item 7. Description:

1 BRAKE VALVE ASSEMBLY

8. Part Number:

274N1051-3

9. Quantity:

1

10. Serial Number:

08694

11. Status/Work:

OVERHAULED

12. Remarks:

The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.

TSC: 0:00 CSO: 0  
SIB and A/D: None Applicable.

OEI CMM: 32-41-03, Revision#: 40, Revision Date: 11/1/2020

**ORIGINAL**

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the item identified above was manufactured in conformity to:

☒ Approved design data and in a condition for return to operation

☐ Not approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

14b. Authorized Signature:

14c. Approve Certificate No.:

77AR783B

13d. Name (Typed or Printed):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

08-Jul-2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.





**Aero Accessories & Repair, Inc.**  
FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954 266 1300,

## Work Order

Work Order #: 57763

Date Printed: 6/8/2023

Time: 10:47:14 AM

Page: 1

**To:**  
AJW AVIATION LTD.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, SLI RH13 0AS  
UNITED KINGDOM

**Ship To:**  
B AND H WORLDWIDE SG PTE LTD  
C/O AJW AVIATION  
70 ALPS AVE  
#01-03 & #02-03  
498801  
SIGNAPORE

Ref #: T41336      Phone #: 305 470 8007      Fax #: 441.403.710.936      Email: louise@ajw-group.com  
Code: 45      Site: SH/DV      PN: 274N1051-3      Descr: BRAKE VALVE ASSEMBLY  
Qty: 1      Station: HYDRAULIC      Make:      Model:      Mfg: \_

Repair Manual(s): 32-41-03 Rev: 40 Rev: Date: 11/1/2020

Entry Date: 5/30/2023      Need Date: 6/14/2023      Compl. Date: 6/8/2023 10:1      Warranty: No      Container:

Serial Numbers: 08694

### RECEIVING INSPECTION

P/N and S/N verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

### PRELIMINARY INSPECTION

P/N 274N1051-3 was verified IAW technical data referenced above.  
S/N 08694 verified through ID plate and customer RO.  
No Ad's applicable at this shop visit.  
TSN: Unk      CSN: Unk      TSO: Unk      CSO: Unk  
Tech: LO #65

### HIDDEN DAMAGE

None noted.  
Tech: LO #65

### INITIAL FINDINGS

Unit failed IAW technical data referenced above.  
Reason: External leakage.  
Customer Complaint: Not verified.  
Tech: LO #65

### TEARDOWN FINDINGS

~~Unit disassembled, cleaned and inspected IAW technical data referenced above. Minor nicks, scratches, and dents do not affect fit, form, or function of the unit. Unit requires replacements of all seals, packings and retainers removed during disassembly. The condition of the slide assy will be determine at final test.~~  
Unit will be overhauled.  
Tech: LO #65

### CORRECTIVE ACTION

All parts listed in teardown report were replaced and findings listed were corrected. Unit was overhauled & tested IAW technical data referenced above.  
Tech: LO #65

Authorized Signature: 

Name: WELCEMEN JEANNOT

Date: 6/8/2023



Aero Accessories & Repair, Inc.

FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300,

## Packing Slip



SH38649

### Aero Accessories & Repair, Inc.

FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300,

Customer: AJW AVIATION LTD.

Shipping Order: SH38649

Order: 57763

Terms: Not determined

Ship Via: FEDEX INTERNATIONAL PRIORITY

Ship Via Acc: 248185260

AWB: 615757321883

Page: 1

Date: 6/8/2023

Time: 1:28:30 PM

Ship To: AJW AVIATION LTD.

C/O AJW AVIATION  
70 ALPS AVE  
#01-03 & #02-03  
498801  
SINGAPORE

Customer PO#: T41336

Order Total: 0

Item	Part Number/Description	Serial Number	Qty	CD
	274N1051-3 BRAKE VALVE ASSEMBLY	08694	1	QH