

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 61943615	
4. Organisation Name and Address: Lufthansa Technik  Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order/Contract/Invoice 61943615	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	MODULE P5-9 WINDOW PITOT HEAT		1	D02979	REPAIRED
12. Remarks TP R MK-No. 10 Pack Code 00 Resp. Workshop 33422031 Workshop Station HAM305					
A.J. Walter (Aviation) Ltd. R406879 Opr. Hours Cycle Opr. Day TT UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0 TASK PERFORMED IN ACCORDANCE WITH CMM 30-09-07 REV. 22 / CMDS 30-09-07 ISSUE 032					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☒ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service. Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents					
13b. Authorised Signature		13c. Approval / Authorisation Number		14b. Authorised Signature 523053	
13d. Name		13e. Date (dd mmm yyyy)		14c. Certificate / Approval Ref. Number DE.145.0001	
				14d. Name Lukas Klawitter	
				14e. Date (dd mmm yyyy) 08 Jun 2023	

Return to Service in Accordance with 14 CFR part 43
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under

FAA Certificate No.: DLAY225D



61943615

3. Form Tracking Number

1. Approving Competent
Authority / CountryCAA
UK

AUTHORISED RELEASE CERTIFICATE

CAA FORM 1

21752959 00000001

4. Organisation Name and Address



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order / Contract / Invoice

61943615

6. Item

7. Description

MODULE P5-9 WINDOW PITOT HEAT

8. Part No.

69-37346-2300

9. Qty.

1

10. Serial No.

D02979

11. Status / Work

REPAIRED

12. Remarks

ATA 3000

TP R

MK-No. 10

Pack Code 00

Resp. Workshop 33422031

Workshop Station HAM305

A.J. Walter (Aviation) Ltd. R406879

	Opr. Hours	Cycle	Opr. Day
TT	UNKNOWN	UNKNOWN	UNKNOWN
TSC	UNKNOWN	UNKNOWN	UNKNOWN
TSF	0	0	0

TASK PERFORMED IN ACCORDANCE WITH CMM 30-09-07 REV. 22 /
CMDS 30-09-07 ISSUE 032☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in
a condition for safe operation☐ non-approved design data specified in block 1214a. ☒ Part -145.A.50 Release to Service☐ Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in
block 12, was accomplished in accordance with Part-145 and in respect to that work the items are
considered ready for release to service.

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

523053

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

Lukas Klawitter

14c. Certificate / Approval Ref. Number

UK.145.01408

14e. Date (dd mmm yyyy)

08 Jun 2023

USER / INSTALLER RESPONSIBILITIES

Note:

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that
his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by
the user/installer before the aircraft may be flown.

CAA Form 1-MF/CAO/145 Issue 1

LHT Form 33081 C-22 (HAM T/TQ-A1)

Workshop Report



Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Lufthansa Technik

Customer Order No. R406879

61943615

Certificate Ref. No.

21752959 00000001

Work Order/Contract/Invoice
61943615

Part. No. as received
69-37346-2300

Serial No. as received

D02979

Part No. as dispatched
69-37346-2300

Serial No. as dispatched

D02979

Reason for removal
RFR: ANTI - ICE MASTER CAUTION LIGHT INOP

Findings

Reason for removal confirmed.
Printed circuit card A5 defective.
Push to test indicators L2, L4, L6 defective.
Cap-assys of push to test indicators L9, L3, L19, L1, L20 defective.

Action

Incoming inspection and test according to specifications performed.

Printed circuit card A5 replaced.
Push to test indicators L2, L4, L6 replaced.
Cap-assys of push to test indicators L9, L3, L19, L1, L20 replaced.

Unit cleaned, repaired and tested.

Outgoing condition:
Relatively to the age, unit has normal wear and tear. Form, fit, function is not affected.

See Unit Mod-Label if equipped

Description
MODULE P5-9 WINDOW PITOT HEAT

Responsible Workshop
33422031

Modification Status according to Mod-Label

Name

523053, Lukas Klawitter

Date (dd mmm yyyy)

08 Jun 2023

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

RFID-Smartlabel

61943615



Ident-Tag Barcode

Ident-Tag**Lufthansa Technik**Form Tracking Number
21752959 00000001

Work Order / Contract / Invoice

Description
MODULE P5-9 WINDOW PITOT HEATPart. No.
69-37346-2300

Eligibility

Quantity
1Status / Work
REPAIREDSerial-/Batch No.
D02979

Remarks

TP R MK-No. 10
FSCM 81205 ATA 3000

Resp. Workshop 33422031 Workshop Station HAM305

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

RemovedPNR¹SNR¹Position/FIN No.¹Station¹A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹☐ 22 UnscheduledComplaint No.¹ or WO-Reference¹☐ 11 ScheduledFailure Description¹ (Please write in capital letters only)CCI-ID²Stamp or ID Number + Signature^{1/2}Date¹Special Investigation Tag exists ☐ Yes**Please send back to:**(unless other return location is agreed)LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLBUETTEL
Deutschland

(LTLS-Information: Use this box for ZID)

¹ Mandatory entries without using CCI-Mask² Mandatory entries using CCI-Mask

LHT Form 31794 E-20 (FRA T/FS-QP)