


1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking Number. WO131239		
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T39472-1			
6. Item/7. Description:		8. Part Number:		9. Quantity:		10. Serial/Batch Number:	11. Status/Work:
1 AIR TRAFFIC SERVICE UNIT		LA2TGG20503B050		1.00		2T0001397	INSPECTED/TESTED
12. REMARKS UNIT INSPECTED AND TESTED SERVICEABLE AS PER CMM: 46-21-34, Rev:10 Dated: MAY 03 / 2021. FOR MORE INFORMATION REFER TO TEAR DOWN REPORT.							
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17							
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12				14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. <input checked="" type="checkbox"/> CAR 571.10 Maintenance Release <input checked="" type="checkbox"/> Other regulation specified in Block 12			
13b. Signature:		13c. Approved Organization Number		14b. Signature: 		14c. Approval Organization Number 33-12	
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Abderrazak Diab		14e. Date (dd/mm/yyyy) 21/Oct/2022	
Installer Responsibilities							
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.							

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO131239

Date Printed: 21/10/2022

Customer RO: T39472-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: AIR TRAFFIC SERVICE UNIT

Phone:

P/N: LA2T0G20503B050

Qty: 1

Email:

S/N: 2T0001397

Mfg: AIRBUS OPERATIONS

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

P/N Out: LA2T0G20503B050

S/N Out: 2T0001397

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: TEST AND RECERTIFY

Faults:

CODE: NO FAULT FOUND

DETAILS: Unit passed acceptance test two times and no fault found.

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: UNIT INSPECTED AND TESTED SERVICEABLE AS PER CMM: 46-21-34, Rev:10 Dated: MAY 03 / 2021,