

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W23577	
4. Organization Name and Address: General MRO Aerospace 3018 NW 72nd Ave MIAMI, FL 33122 Ph: 305-482-9903, Fax: 305-482-9905 sales@generalmroaerospace.com FAA Approval Holder: 19GR994Y				5. Work Order, Contract or Invoice Number: T27156	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	VALVE ASSY	HTE370001	1	M0359VN	REPAIRED
12. REMARKS: Full details describing the actual work performed are contained and held in W/O # W23577. This unit was Repaired in accordance with: MFG: HIGH TEMPERATURE ATA Manual ID: 36-15-02, Revision #: 4, Revision Date: 1/28/2003 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.6095".					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12			14. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval Authorization No:		14c. Approval/Certificate No: 19GR994Y	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 22/Dec/2015	
[Signature]		[Stamp: GMA 3]		Darius Davis	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



General MRO Aerospace
3018 NW 72nd Ave
MIAMI, FL 33122
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown

Work Order #: W23577

Date Printed: 12/22/2015

Time: 3:01:21 PM

Page: 1

To:

AJW AVIATION LTD
VISCOUNT HOUSE WEST SUSSEX
Sussex, UK RH13 8RA

Ship To:

AJW AVIATION LTD
AJ WALTER AVIATION LTD
The Headquarters
Maydwell Avenue
West Sussex, Slinfold RH13 0AS
UNITED KINGDOM

Ref #: T27156

Phone #: 441403711777

Fax #: 441403710936

Email: lyudmyla.oliynyk@ajw-aviation.com

Code: 165

Site: KV

PN: HTE370001

Descr: VALVE ASSY

Qty: 1

Make:

Model:

Mfg: HIGH TEMPERATUR

Serial Number: M0359VN

Entry Date: 11/18/2015

Need Date: 11/23/2015

Compl. Date: 12/21/2015 3:4

Warranty: No

Container:

ATA: 36-15-02 Loc: 2550 Revision: 4 Rev Date: 11/28/2003

REMARKS

SUBCOMPONENT PN AND SN

N/A

REASON FOR REMOVAL

NONE GIVEN.

PRELIMINARY INSPECTION

Verified PN and SN on unit and RO.

PRE TEST (YES/NO)

Unit failed functional tests due to leakage from foreign matter.

HIDDEN DAMAGE

N/A

TEARDOWN FINDINGS

During teardown inspection the following discrepancies were found:
Unit was cleaned and inspected. Upon inspection found foreign matter preventing valve flap closure. Unit requires deep cleaning and reconditioning for Repair.

Discrepancies Noted:

1. Foreign matter preventing valve flap closure- Requires rework

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is [X] Approved || Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Authorized Signature:

Inspector Seal:

Date: 12/22/2015

Darius Davis



**General MRO Aerospace**

3018 NW 72nd Ave
MIAMI, FL 33122
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown**Work Order #: W23577**

Date Printed: 12/22/2015

Time: 3:01:22 PM

Page: 2

To:

AJW AVIATION LTD
VISCOUNT HOUSE WEST SUSSEX
Sussex, UK RH13 8RA

Ship To:

AJW AVIATION LTD
AJ WALTER AVIATION LTD
The Headquarters
Maydwell Avenue
West Sussex, Slinfold RH13 0AS
UNITED KINGDOM

Ref #: T27156

Phone #: 441403711777

Fax #: 441403710936

Email: lyudmyla.oliynyk@ajw-aviation.com

Code: 165

Site: KV

PN: HTE370001

Descr: VALVE ASSY

Qty: 1

Make:

Model:

Mfg: HIGH TEMPERATUR

Serial Number: M0359VN

Entry Date: 11/18/2015

Need Date: 11/23/2015

Compl. Date: 12/21/2015 3:5

Warranty: No

Container:

ATA: 36-15-02 Loc: 2550 Revision: 4 Rev Date: 11/28/2003

Rework Required:

1. Deep Cleaning
2. Reconditioning

Repair quote.

Technician: Hector Garcia

Inspector: Cristian Munoz

Date: 12/15/2015.

AD/SERVICE BULLETINS/MODIFICATIONS

No AD applicable to this unit.

WORK PERFORMED

Performed cleaning. Unit was tested and passed all functional test. Unit has been Repaired in accordance with current HIGH TEMPERATURE ENGINEERS CMM 36-15-02 REV 4 DTD November 28, 2003.

Technician: Hector Garcia

Inspector: Cristian Munoz

Date: 12/21/2015.

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
[X] Approved || Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Authorized Signature:

Inspector Seal:

Date: 12/22/2015

Darius Davis